























NHC41231020电柜 (62批中有三件)

序号	订单	台车号	简图	数量	颜色	检查内容	
1	H2B069A01	2		2	三价镀锌	①确认颜色正确 ②确认无毛刺	☒ ☒
2	H2A959A01	2		1	三价镀锌	①确认颜色正确 ②确认无毛刺	☒ ☒
3	H2601169A02	2		1	三价镀锌	①确认颜色正确 ②确认无毛刺	☒ ☒
4	H2601182A02	2		1	三价镀锌	①确认颜色正确 ②确认无毛刺	☒ ☒
5	H2601247A01	2		1	三价镀锌	①确认颜色正确 ②确认无毛刺	☒ ☒
6	H2602535A01	2		1	三价镀锌	①确认颜色正确 ②确认无毛刺	☒ ☒
7	H2B062A02	2		1	灰皱	①确认颜色正确 ②确认无毛刺	☒ ☒
8	H2601271A01	2		2	灰皱	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒
9	H2601138C06	2		1	三价镀锌	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒
10	H2601143A01	2		1	三价镀锌	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒

11	H2601176A01	2		1	三价镀锌	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	
12	H2601233A01	2		1	三价镀锌	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	
13	H2601275A02	2		1	三价镀锌	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	
14	H2601468A02	2		1	三价镀锌	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	
15	H2601278A01	2		1	三价镀锌	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	
16	H2601338A01	2		1	三价镀锌	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	
17	H8306196A02	2		1	灰皱	①确认颜色正确 ②确认无毛刺	☒ ☐	
18	H2601352A02	2	焊在柜上	1		①确认颜色正确 ②确认无毛刺	☒ ☐	
19	H2601465A01	2		1	三价镀锌	①确认颜色正确 ②确认无毛刺	☒ ☐	
20	H2602516A02(2/5)	2	柜	1		①确认颜色正确 ②确认无毛刺	☒ ☐	
21	H2602516A02(3/5)	2	柜	1		①确认颜色正确 ②确认无毛刺	☒ ☐	

22	H2602516A02(4/5)	2	柜	1		①确认颜色正确 ②确认无毛刺	☒ ☐	
23	H2602516A02(5/5)	2	柜	2		①确认颜色正确 ②确认无毛刺	☒ ☐	
24	H2601147B01	2		1	灰皱	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☐ ☐ ☐	
25	H2601144A01	2		1	灰皱	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☐ ☐	
26	H2601177B03	2		1	灰皱	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	
27	H2601470A01	2		1	灰皱	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	
28	H2601276A03	2		1	灰皱	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	
29	H2601140C08	2		1	二价镀锌	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	
30	5620925	2		1	灰皱	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	