























ALC25250504+0505电柜 (第四批)

序号	台车号	型式	简图	数量	颜色	检测内容	备注
1	1	I48750D04 D14		1		①确认颜色正确 ②确认无毛刺	☒ ☒
2	1	5517549		1	灰皱	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒
3	1	5517550		1	灰皱	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒
4	1	5517551		1	灰皱	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒
5	1	5517553		2	灰皱	①确认颜色正确 ②确认无毛刺	☒ ☒
6	1	5517555		1	灰皱	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒
7	1	5517561		1	三价镀锌	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒
8	1	5517562		1	三价镀锌	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒
9	1	5517563		1	三价镀锌	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒
10	1	5517564		1	三价镀锌	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒
11	1	5517565		1	三价镀锌	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒

12	1	5517566		1	三价镀锌	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	
13	1	5517567		1	三价镀锌	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	
14	1	5517568		1	三价镀锌	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	
15	1	5517569		1	三价镀锌	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	左右各1件
16	1	5517570		2	三价镀锌	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	
17	1	H2B050A02		1	三价镀锌	①确认颜色正确 ②确认无毛刺	☒ ☒	
18	1	5517560		1	三价镀锌	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	
19	1	H2A901A01		2	三价镀锌	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	NBR
20	1	5517532		1		确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	
21	1	5517533	焊在柜上	1		①确认颜色正确 ②确认无毛刺	☒ ☒	
22	1	5517535	焊在柜上	1		①确认颜色正确 ②确认无毛刺	☒ ☒	

23	1	5517536	焊在柜上	1		①确认颜色正确 ②确认无毛刺	☒ ☒	
24	1	5517537	焊在柜上	1		①确认颜色正确 ②确认无毛刺	☒ ☒	
25	1	5517538	焊在柜上	1		①确认颜色正确 ②确认无毛刺	☒ ☒	
26	1	5517539	焊在柜上	1		①确认颜色正确 ②确认无毛刺	☒ ☒	
27	1	5517540	焊在柜上	1		①确认颜色正确 ②确认无毛刺	☒ ☒	
28	1	5517541	焊在柜上	1		①确认颜色正确 ②确认无毛刺	☒ ☒	
29	1	5517542	焊在柜上	1		①确认颜色正确 ②确认无毛刺	☒ ☒	
30	1	5517544	焊在柜上	1		①确认颜色正确 ②确认无毛刺	☒ ☒	
31	1	5537196	焊在柜上	1		①确认颜色正确 ②确认无毛刺	☒ ☒	
32	1	5537197	焊在柜上	1		①确认颜色正确 ②确认无毛刺	☒ ☒	
33	1	5517545	焊在柜上	1		①确认颜色正确 ②确认无毛刺	☒ ☒	

34	1	5517546	焊在柜上	1		①确认颜色正确 ②确认无毛刺	☒ ☒	
35	1	5517547	焊在柜上	1		①确认颜色正确 ②确认无毛刺	☒ ☒	
36	1	5517548	焊在柜上	1		①确认颜色正确 ②确认无毛刺	☒ ☒	
37	1	5548006		2	灰皱	①确认颜色正确 ②确认无毛刺	☒ ☒	
38	1	X10334A02		3	R海绵 T	①确认颜色正确 ②确认无毛刺	☒ ☒	
39	1	X10262A02		2	R海绵 T	①确认颜色正确 ②确认无毛刺	☒ ☒	
40	1	5548892		1	灰皱	①确认颜色正确 ②确认无毛刺	☒ ☒	
41	1	5549869		1	灰皱	①确认颜色正确 ②确认无毛刺	☒ ☒	
42	1	5549870		1	灰皱	①确认颜色正确 ②确认无毛刺	☒ ☒	
43	1	5517579		1	三价镀锌	①确认颜色正确 ②确认无毛刺	☒ ☒	
44	1	5517580		1	灰皱	①确认颜色正确 ②确认无毛刺	☒ ☒	

45	1	5518903		1	灰皱	①确认颜色正确 ②确认无毛刺	☒ ☒
----	---	---------	---	---	----	-------------------	--