


















序号	物料号	台车号	简图	数量	颜色	检查内容	备注
1	H2602535A01	2		1	三价镀锌	①确认颜色正确 ②确认无毛刺	☒ ☒
2	H2601789A01	2		1	三价电镀	①确认颜色正确 ②确认无毛刺	☒ ☒
3	H2601844B01	2		1	三价电镀	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒
4	H2601668A03	2		1	灰皱	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒
5	H2601955A01	2		1	灰皱	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒
6	H2601431A01	2		1		确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒
7	H65132D01	2		1	电镀	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒
8	H2602002A02	2		1	黑皱	①确认颜色正确 ②确认无毛刺	☒ ☒
9	H1100576A01	2		1	会在	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒
10	H2601900A02	2		1	黑皱	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒

11	H6500355A02	2		1	黑皱	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	
12	H6500356A01	2		1	黑皱	①确认颜色正确 ②确认无毛刺	☒ ☒	
13	H8302369B02	2		1	黑平	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	
14	H2601991A01	2		1	灰皱	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	
15	H2601467A02	2		1	三阶电镀	①确认颜色正确 ②确认无毛刺	☒ ☒	
16	H1100577A01	2		1	灰皱	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	
17	H1100585A02	2		1	灰皱	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	
18	H2601898A02	2		1	黑皱	①确认颜色正确 ②确认无毛刺	☒ ☒	
19	H2601182A02	11		1	三价镀锌	①确认颜色正确 ②确认无毛刺	☒ ☒	