






























电柜NHC81230906第十四批

序号	物料号	台车号	简图	数量	颜色	检查内容	备注
1	H26530A01	2	部件焊接在柜体上，无需下料	2	#N/A	①确认颜色正确 ②确认无毛刺	☒ ☒
2	5147586[001](1/4	2	焊在箱子上	1	#N/A	①确认颜色正确 ②确认无毛刺	☒ ☒
3	5147586[001](2/4	2	焊在箱子上	1	#N/A	①确认颜色正确 ②确认无毛刺	☒ ☒
4	5147586[001](3/4	2	焊在箱子上	1	#N/A	①确认颜色正确 ②确认无毛刺	☒ ☒
5	5147586[001](4/4	2	焊在箱子上	1	#N/A	①确认颜色正确 ②确认无毛刺	☒ ☒
6	H26702B01	2	焊在箱子上	2	#N/A	①确认颜色正确 ②确认无毛刺	☒ ☒
7	H2601707A01	2		2	灰皱	①确认颜色正确 ②确认无毛刺	☒ ☒
8	R24945A02	2	门轴	4	部件已焊接在柜	①确认颜色正确 ②确认无毛刺	☒ ☒
9	5147595[001]	2	无图贴在4035柜体上	1	#N/A	①确认颜色正确 ②确认无毛刺	☒ ☒
10	H2A959A01	2		1	三价镀锌	①确认颜色正确 ②确认无毛刺	☒ ☒
11	H2601247A01	2		1	三价镀锌	①确认颜色正确 ②确认无毛刺	☒ ☒

12	H2601776A02	1		1	灰皱	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	
13	H6500356A01	1		1	黑皱	①确认颜色正确 ②确认无毛刺	☒ ☐	
14	5147564[001]	2		1	#N/A	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☐ ☐ ☐ ☒	
15	5109230[002]	2		1	灰皱	①确认颜色正确 ②确认无毛刺	☐ ☒	
16	R20410A01	1		2	需要王震提供	①确认颜色正确 ②确认无毛刺	☐ ☒	
17	5109280[001]	2		1	灰皱	①确认颜色正确 ②确认无毛刺	☐ ☒	
18	H2601703A01	2		2	三价镀锌	①确认颜色正确 ②确认无毛刺	☐ ☒	
19	H2601704A01	2		2	三价镀锌	①确认颜色正确 ②确认无毛刺	☒ ☒	
20	H2601728A01	2		1	三价镀锌	①确认颜色正确 ②确认无毛刺	☐ ☒	
21	H2601729A01	2		1	三价镀锌	①确认颜色正确 ②确认无毛刺	☒ ☒	
22	5109243[001]	2		1	三价镀锌	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☐ ☒ ☒ ☒	

23	5109276[001]	2		1	三价镀锌	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	
24	5109277[001]	2		1	三价镀锌	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	
25	5109278[001]	2		1	三价镀锌	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	
26	5109272[001]	2		1	三价镀锌	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	
27	5109268[001]	2		1	三价镀锌	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	
28	5109273[001]	2		1	三价镀锌	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	
29	H2601727A01	2		8	三价镀锌	①确认颜色正确 ②确认无毛刺	☒ ☒	
30	H2601726A01	2		4	三价镀锌	①确认颜色正确 ②确认无毛刺	☒ ☒	
31	H2602006A0202	2		1	#N/A	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	
32	H2601725A01	2		2	三价镀锌	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	
33	5126759[002]	2		1	三价镀锌	①确认颜色正确 ②确认无毛刺	☒ ☒	

34	5109283[001]	2		1	灰皱	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	
35	5127529[001]	2		1	灰皱	①确认颜色正确 ②确认无毛刺	☒ ☒	
36	5109282[001]	2		1	灰皱	①确认颜色正确 ②确认无毛刺	☒ ☒	
37	5181909	2		1	三价镀锌	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	
38	5181986	2		1	灰皱	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	
39	5147915[001]	2		1	灰皱	①确认颜色正确 ②确认无毛刺	☒ ☒	