









































电柜NHC81251001第批

序号	物料号	内部号	简图	数量	颜色	检查内容	备注
1	5148266	4085			灰皱	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒
2	5147595	#N/A	无图贴在4035柜体上	1	#N/A	①确认颜色正确 ②确认无毛刺	☒ ☒
3	H26530A01	4463	部件焊接在柜体上, 无需下料	2	#N/A	①确认颜色正确 ②确认无毛刺	☒ ☒
4	5147564	#N/A	焊在箱子上	1	#N/A	①确认颜色正确 ②确认无毛刺	☒ ☒
5	5147586(1/4)	#N/A	焊在箱子上	1	#N/A	①确认颜色正确 ②确认无毛刺	☒ ☒
6	5147586(2/4)	#N/A	焊在箱子上	1	#N/A	①确认颜色正确 ②确认无毛刺	☒ ☒
7	5147586(3/4)	#N/A	焊在箱子上	1	#N/A	①确认颜色正确 ②确认无毛刺	☒ ☒
8	5147586(4/4)	#N/A	焊在箱子上	1	#N/A	①确认颜色正确 ②确认无毛刺	☒ ☒
9	H2A959A01	3729		1	三价镀锌	①确认颜色正确 ②确认无毛刺	☒ ☒
10	H2601247A01	3733		1	三价镀锌	①确认颜色正确 ②确认无毛刺	☒ ☒
11	H6500356A01	3765		1	黑皱	①确认颜色正确 ②确认无毛刺	☒ ☒

12	5109230	4036		1	灰皱	①确认颜色正确 ②确认无毛刺	☒ ☒	
13	H2601707A01	4037		2	灰皱	①确认颜色正确 ②确认无毛刺	☒ ☒	
14	R20410A01	4038		2	需要王震提供	①确认颜色正确 ②确认无毛刺	☒ ☒	
15	5109280	4040		1	灰皱	①确认颜色正确 ②确认无毛刺	☒ ☒	
16	H2601703A01	4041		2	三价镀锌	①确认颜色正确 ②确认无毛刺	☒ ☒	
17	H2601704A01	4042		2	三价镀锌	①确认颜色正确 ②确认无毛刺	☒ ☒	
18	H2601728A01	4043		1	三价镀锌	①确认颜色正确 ②确认无毛刺	☒ ☒	
19	H2601729A01	4044		1	三价镀锌	①确认颜色正确 ②确认无毛刺	☒ ☒	
20	5109243	4046		1	三价镀锌	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	
21	5109276	4047		1	三价镀锌	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	
22	5109277	4048		1	三价镀锌	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	

23	5109278	4049		1	三价镀锌	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	
24	5109272	4050		1	三价镀锌	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	
25	5109268	4051		1	三价镀锌	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	
26	5109273	4052		1	三价镀锌	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	
27	H2601727A01	4053		8	三价镀锌	①确认颜色正确 ②确认无毛刺	☒ ☒	
28	H2601726A01	4054		4	三价镀锌	①确认颜色正确 ②确认无毛刺	☒ ☒	
29	H2602006A02	4055		1	#N/A	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	
30	H2601725A01	4056		2	三价镀锌	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	
31	5126759	4057		1	三价镀锌	①确认颜色正确 ②确认无毛刺	☒ ☒	
32	5109283	4058		1	灰皱	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	
33	5127529	4059		1	灰皱	①确认颜色正确 ②确认无毛刺	☒ ☒	

34	5109282	4060		1	灰皱	①确认颜色正确 ②确认无毛刺	☒ ☒	
35	5181909	4061		1	三价镀锌	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	
36	5181986	4062		1	灰皱	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	
37	R24945A02	4063	门轴	4	部件已焊接在柜	①确认颜色正确 ②确认无毛刺	☒ ☒	
38	5147915	4066		1	灰皱	①确认颜色正确 ②确认无毛刺	☒ ☒	
39	H2602001A01	4077		1	黑皱	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	
40	H6500362A01	4078		1	黑皱	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	
41	H2601721A01	4083		1	三价镀锌	①确认颜色正确 ②确认无毛刺	☒ ☒	
42	H65132D01	4084			三价镀锌	①确认颜色正确 ②确认无毛刺	☒ ☒	
43	5109251	4374		1	三价镀锌	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	
44	5135818	4376		1	灰皱	①确认颜色正确 ②确认无毛刺	☒ ☒	

45	5147910	4377		1	灰皱	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	
46	H1100637A01	4378		1	黑色	①确认颜色正确 ②确认无毛刺	☒ ☒	
47	H1100638A01	4379		1	黑色	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	
48	H2601737A01	4380		1	灰皱	①确认颜色正确 ②确认无毛刺	☒ ☒	
49	5109241	4382		1	黑皱	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	
50	H26702B01	4464	焊在箱子上	2	#N/A	①确认颜色正确 ②确认无毛刺	☒ ☒	
51	A4091	#N/A				门锁王震别忘了		