





























NH163260601电柜- (5批)

序号	物料号	台	简图	数量	颜色	检查内容	备注
1	H2601638	1		1	灰皱	确认颜色正确 确认无毛刺 确认无变形 过丝确认	装配
2	H2601638B01(2/4)	1	无图贴在3722柜体上	1	灰皱	①确认颜色正确 ②确认无毛刺	
3	H2601638B01(3/4)	1	无图贴在3722柜体上	1	灰皱	①确认颜色正确 ②确认无毛刺	
4	H2601638B01(4/4)	1	无图贴在3722柜体上	1	灰皱	①确认颜色正确 ②确认无毛刺	
5	H2601853A01	1	无图贴在3722柜体上	2	三价镀锌	①确认颜色正确 ②确认无毛刺	
6	H2601795A01	1	无图贴在3722柜体上	1	三价镀锌	确认颜色正确 确认无毛刺 确认无变形 过丝确认	
7	H2601645A02	1		1	灰皱	①确认颜色正确 ②确认无毛刺	
8	H2601646A02	1		2	灰皱	①确认颜色正确 ②确认无毛刺	
9	H2601639A03	1		1	灰皱	①确认颜色正确 ②确认无毛刺	NBR
10	H2B069A01	1		2	三价镀锌	①确认颜色正确 ②确认无毛刺	
11	H2A959A01	1		1	三价镀锌	①确认颜色正确 ②确认无毛刺	

12	H2601782A01	1		2	三价镀锌	①确认颜色正确 ②确认无毛刺	☒ ☒	
13	H2601169A02	1		1	三价镀锌	①确认颜色正确 ②确认无毛刺	☒ ☒	发
14	H2601182A02	1		1	三价镀锌	①确认颜色正确 ②确认无毛刺	☒ ☒	发
15	H2601247A01	1		1	三价镀锌	①确认颜色正确 ②确认无毛刺	☒ ☒	
16	H2601788B02	1		1	三价镀锌	①确认颜色正确 ②确认无毛刺	☒ ☒	
17	H2601633A06	1		1	三价镀锌	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	
18	H2601635A04	1		1	三价镀锌	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	
19	H2601636A09	1		1	三价镀锌	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	
20	H2601637A01	1		1	三价镀锌	①确认颜色正确 ②确认无毛刺	☒ ☒	
21	H2601654A02	1		1	灰皱	①确认颜色正确 ②确认无毛刺	☒ ☒	
22	H2601791A01	1		1	灰皱	①确认颜色正确 ②确认无毛刺	☒ ☒	NBR

23	H2601787A04	1		1	三价镀锌	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	
24	H2601794A01	1		1	三价镀锌	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	
25	5180360	1		1	灰皱	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	
26	H2601666A02	1		1	灰皱	①确认颜色正确 ②确认无毛刺	☒ ☒	
27	5180359	1		1	灰皱	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	
28	H2601792A02	1		1	灰皱	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	发
29	H2601648A04	1		1	灰皱	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	
30	H2601649A03	1		1	灰皱	①确认颜色正确 ②确认无毛刺	☒ ☒	
31	H2601660A03	1		1	灰皱	①确认颜色正确 ②确认无毛刺	☒ ☒	
32	H2602016A03	1		1	光泽镀锌	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	
33	H2602018A01	1		1	灰皱	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	

34	H2601298A01	1		1	光泽镀锌	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	
35	H2601652A02	1		1	光泽镀锌	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	