
































ALC25251001-1101(33批) 本体

序号	T号	型式	简图	数量	颜色	检测内容	备注
1	2	5406534		1	发丝件	①确认颜色正确 ②确认无毛刺	☒ ☒ B
2	2	5413214		1	白平	①确认颜色正确 ②确认无毛刺	☒ ☒ B
3	2	H0004079A01		1	黑平	①确认颜色正确 ②确认无毛刺	☒ ☒ B
4	2	H0504764A02		1	发黑	①确认颜色正确 ②确认无毛刺	☒ ☒ B
5	2	H0504766A01		1	发黑	①确认颜色正确 ②确认无毛刺	☒ ☒ B
6	2	H0504768A03		1	发丝件	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒ B
7	2	H0504918A02		1	发黑	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒ B
8	2	H0504919A03		1	发黑	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒ B
9	2	H0504920A03		1	灰皱	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒ A
10	2	H1501989A02		1	黑染	①确认颜色正确 ②确认无毛刺	☒ ☒ B

11	2	H1502817A01		1	发黑	①确认颜色正确 ②确认无毛刺	☒ ☒	B
12	2	H1502951A02		1	发黑	①确认颜色正确 ②确认无毛刺	☒ ☒	装配
13	2	H1502999A01		1	灰皱			
14	2	H1605084A01		1	黑平	①确认颜色正确 ②确认无毛刺	☒ ☒	B
15	2	H1605384A01		1	白平	①确认颜色正确 ②确认无毛刺	☒ ☒	A
16	2	H1605388B02		1	白平	①确认颜色正确 ②确认无毛刺	☒ ☒	B
17	2	H3001586A01		1	黑平	①确认颜色正确 ②确认无毛刺	☒ ☒	B
18	2	H3101443A01		1	白皱	①确认颜色正确 ②确认无毛刺	☒ ☒	B
19	2	H3101444A01		1	发黑	①确认颜色正确 ②确认无毛刺	☒ ☒	B
20	2	H3201811A02		1	白平	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	A
21	2	H3201812B01		1	白平	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	A

22	2	H8202986B01		1	白平	①确认颜色正确 ②确认无毛刺	☒ ☒	A
23	2	H0504767C02		1	发黑	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	B
24	2	H1605648A02		1	灰皱	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	B
25	2	H8202823A02		1	黑色	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	B装配
26	2	5407696		1	巴普	①确认颜色正确 ②确认无毛刺	☒ ☒	A
27	2	H1605617B01		1	白皱	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	组合
28	2	H8202881B01		1	白皱	①确认颜色正确 ②确认无毛刺	☒ ☒	组合发
29	2	5493082		1	黑染	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	B
30	2	5491336		1	发丝件	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	B
31	2	5513540		1	黑染	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	B
32	2	5524456		1	白皱	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	A

33	2	5619498		1	黑染	①确认颜色正确 ②确认无毛刺	☒ ☐	B
----	---	---------	--	---	----	-------------------	---	---