


































NHC81261001电柜 (10批)

序号	小图	物料名称	数量	颜色	检查内容	备注
1		H2A959A01	1	三价镀锌	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☐ 装配
2		H2601247A01	1	三价镀锌	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☐ 装配
3		H6500356A01	1	黑皱	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒
4		5109230	1	灰皱	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒ 装配
5		H2601707A01	2	灰皱	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒ 装配
6	无照片	R20410A01	2		确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☐ 装配
7		5109280	1	灰皱	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☐ 装配
8		H2601703A01	2	三价镀锌	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☐ 装配
9		H2601704A01	2	三价镀锌	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒ 装配
10		H2601728A01	1	三价镀锌	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☐ 装配

11		H2601729A01	1	三价镀锌	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	装配
12		5109243	1	三价镀锌	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	装配
13		5109276	1	三价镀锌	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	装配
14		5109277	1	三价镀锌	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	装配
15		5109278	1	三价镀锌	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	装配
16		5109272	1	三价镀锌	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	装配
17		5109268	1	三价镀锌	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	装配
18		5109273	1	三价镀锌	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	装配
19		H2601727A01	8	三价镀锌	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	装配
20		H2601726A01	4	三价镀锌	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	装配
21		H2602006A02	1	三价镀锌	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	装配

22		H2601725A01	2	三价镀锌	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☐ ☒ ☐	装配
23		5126759	1	三价镀锌	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☐ ☐ ☒ ☐	装配
24		5109283	1	灰皱	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☐ ☐ ☐	装配
25		5127529	1	灰皱	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☐ ☐	装配
26		5109282	1	灰皱	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☐ ☒ ☒ ☐	装配
27		5181909	1	三价镀锌	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☐ ☐ ☐	装配
28		5181986	1	灰皱	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☐ ☐ ☐ ☒	
29	无简图	R24945A02	4		确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☐ ☒ ☐	
30		5147915	1	灰皱	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☐ ☐ ☐	遮蔽装配
31		H2602001A01	1	黑皱	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☐ ☐ ☐ ☒	装配
32		H6500362A01	1	黑皱	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☐ ☐ ☒	密封焊接

33		H2601721A01	1	三价镀锌	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	
34	无简图	5148266	1		确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	装配
35		5135818	1	灰皱	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	装配
36		5147910	1	灰皱	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	装配
37		H1100637A01	1	黑平	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	装配密封
38		H1100638A01	1	黑平	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	装配
39		H2601737A01	1	灰皱	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	装配
40		5109241	1	灰皱	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	装配遮蔽
41	无简图	5147595	1		确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	
42	无简图	H26530A01	2		确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	
43	无简图	H26702B01	2		确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	

44	无简图	5147564	1		确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	
45		5763050	1	三价镀锌	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	装配