















































NHC10260301-0304电柜- (第40批) 4台

序号	内部号	型式	简图	数量	颜色	检测内容	备注
1	3724	H2601853A01	无图贴在3722柜体上	4	三阶电镀	①确认颜色正确 ②确认无毛刺	装配
2	3729	H2A959A01		1	三阶电镀	①确认颜色正确 ②确认无毛刺	装配
3	3730	H2601782A01		2	三阶电镀	①确认颜色正确 ②确认无毛刺	装配
4	3759	H2601776A02		1	灰皱	确认颜色正确 确认无毛刺 确认无变形 过丝确认	装配
5	4038	R20410A01		2	需要土震拔	①确认颜色正确 ②确认无毛刺	
6	4375	5112632		1	黑皱	确认颜色正确 确认无毛刺 确认无变形 过丝确认	装配
7	4378	H1100637A01		1	黑平	①确认颜色正确 ②确认无毛刺	装配
8	4379	H1100638A01		1	黑平	①确认颜色正确 ②确认无毛刺	装配
9	4654	5449492		1	灰皱	确认颜色正确 确认无毛刺 确认无变形 过丝确认	装配
10	4655	H2601868A01		4	焊在电柜	①确认颜色正确 ②确认无毛刺	装配
11	4656	H2601869A01		1	焊在电柜	①确认颜色正确 ②确认无毛刺	装配

12	4657	H2601870A01		2	焊在电柜	①确认颜色正确 ②确认无毛刺	☒ ☐	装配
13	4658	H2601884A01		2	焊在电柜	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☐	装配
14	4659	H2601890A01		2	焊在电柜	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☐	装配
15	4660	5212277		1	灰皱	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☐	
16	4664	H2601873A02		1	灰皱	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☐	装配
17	4666	H2601874A01		1	三阶电镀	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☐	装配
18	4667	H2601875A01		1	三阶电镀	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☐	装配
19	4668	H2601876A01		1	三阶电镀	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☐	装配
20	4669	H2601878B01		1	三阶电镀	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☐	
21	4671	X33470B01		1	三阶电镀	①确认颜色正确 ②确认无毛刺	☒ ☐	装配
22	4672	H2601883A02		1	三阶电镀	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☐	装配

23	4673	H2601880A02		1	三阶电镀	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	装配
24	4675	H2A947A03		1	三阶电镀	①确认颜色正确 ②确认无毛刺	/ ☒ ☒	装配
25	4676	5494824		1	三阶电镀	①确认颜色正确 ②确认无毛刺	/ ☒ ☒	装配
26	4677	H2601881A01		1	三阶电镀	①确认颜色正确 ②确认无毛刺	/ ☒ ☒	装配
27	4678	H2601882A01		1	三阶电镀	①确认颜色正确 ②确认无毛刺	/ ☒ ☒	装配
28	4679	H2B019A01		1	三阶电镀	①确认颜色正确 ②确认无毛刺	/ ☒ ☒	装配
29	4680	H2601871A01		1	三阶电镀	①确认颜色正确 ②确认无毛刺	/ ☒ ☒	装配
30	4681	H2B021B01		5	三阶电镀	①确认颜色正确 ②确认无毛刺	/ ☒ ☒	装配
31	4682	H2B022B01		1	三阶电镀	①确认颜色正确 ②确认无毛刺	/ ☒ ☒	装配
32	4683	5169271		1	三阶电镀	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	装配
33	4684	H2602035A01		1	三阶电镀	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	装配

34	4687	H2601051A01		1	三阶电镀	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☐ ☐ ☐	装配
35	4688	H2601052A01		1	三阶电镀	①确认颜色正确 ②确认无毛刺	☒ ☐	装配
36	4689	H2601886A01		1	灰皱	①确认颜色正确 ②确认无毛刺	☒ ☐	装配
37	4690	H2601887B01		1	灰皱	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☐ ☐ ☐	装配
38	4692	H2601891A01		1	灰皱	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☐ ☐ ☐	装配
39	4693	H2A960A01		1	三阶电镀	①确认颜色正确 ②确认无毛刺	☒ ☐	装配
40	4694	H2A961A02		1	三阶电镀	①确认颜色正确 ②确认无毛刺	☒ ☐	装配
41	4695	H2601895A01		2	灰皱	①确认颜色正确 ②确认无毛刺	☒ ☐	装配
42	4697	X33607A01		1	三阶电镀	①确认颜色正确 ②确认无毛刺	☒ ☐	装配
43	4699	H2602061A01		2	灰皱	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☐ ☐ ☐	
44	4702	H2601785A03		1	黑平	①确认颜色正确 ②确认无毛刺	☒ ☐	装配

45	4703	H2601754A04		1	黑平	①确认颜色正确 ②确认无毛刺	☒ ☒	装配
46	4704	5382482		1	黑皱	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	装配
47	4705	5382484		1	黑皱	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	装配
48	5325	H2602034A02		1	三阶电镀	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	
49	#N/A	NHC10000-PC板		1	PC	①确认颜色正确 ②确认无毛刺	☒ ☒	