












NHC5500-先行 (第批)

序号	物料号	T号	简图	数量	颜色	检查内容	备注
1	H8303923D02	3		1	灰皱	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒ 测漏 打胶 装配
2	H8303949D01	3		1	黑平	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒ 测漏 打胶 装配
3	H8304616B01	3		1	灰皱	①确认颜色正确 ②确认无毛刺	☒ ☒
4	H8302029C01	3		1	黑平	①确认颜色正确 ②确认无毛刺	☒ ☒
5	5310872	3		1	不涂装	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒
6	5314392	3		1	不涂装	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒
7	5313272	3		1	不涂装	①确认颜色正确 ②确认无毛刺	☒ ☒
8	5314391	3		1	不涂装	①确认颜色正确 ②确认无毛刺	☒ ☒
9	H8303938B03	3		1	白皱	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒
10	H8304084B03	3		1	灰皱	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒ A

11	H8303936A03	3		1	白皱	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☐ ☐ ☐ ☐	装配 密	B
12	H8303944A04	3		1	黑平	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒		B
13	5333913	3		1	灰皱	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒		A