




















NHC5500-先行 (第批)

NHC5500-先行（第批）									
序号	物料号	T号	简图	数量	颜色	检查内容		备注	
1	H8303924C02	2		1	黑平	①确认颜色正确 ②确认无毛刺	☒ ☐		B
2	H8303927A07	2		1	黑平	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☐ ☐ ☐		B
3	H8303928B02	2		1	黑平	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☐ ☐ ☐	装配	B
4	H1403652D01	2		1	黑平	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☐ ☐ ☐		B
5	H8307554A02	2		1	黑平	①确认颜色正确 ②确认无毛刺	☒ ☐		B
6	H0400591A03	2		1	黑平	①确认颜色正确 ②确认无毛刺	☒ ☐		B
7	H8303922A02	2		1	黑平	①确认颜色正确 ②确认无毛刺	☒ ☐		B
8	H8303939A03	2		2	黑平	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☐ ☐ ☐ ☐		B
9	5279824	2		1	灰皱	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☐ ☐ ☐	A	A
10	H8303926A03	2		1	黑平	①确认颜色正确 ②确认无毛刺	☒ ☐		B

11	H8304577A04	2		1	黑平	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒		B
12	H8303940B01	2		1	黑平	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒		B
13	H0400592A02	2		2	黑平	①确认颜色正确 ②确认无毛刺	☒ ☒		B
14	H0400739A01	2		1	黑平	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒		
15	H47480A01	2		1	黑平	①确认颜色正确 ②确认无毛刺	☒ ☒		B
16	H0400589A01	2		2	黑平	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒		B
17	H8303934B03	2		1	白皱	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒		B
18	H1403027A01	2		1	黑平	①确认颜色正确 ②确认无毛刺	☒ ☒		B
19	H8302030C03	2		1	黑平	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	A装配	B
20	H0102690B02	2		1	黑平	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒		B
21	H8303925B01	2		1	黑平	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒		B

22	H1403650B02	2		1	黑平	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☐ ☒ ☒ ☒ ☐		B
----	-------------	---	---	---	----	----------------------------------	--	--	---