



































序号	内部号	小图	物料名称	数量	颜色	检查内容	
1	DMG3729		H2A959A01	1	三价镀锌	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☐ ☐ ☐
2	DMG3733		H2601247A01	1	三价镀锌	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☐ ☐ ☐ ☒
3	DMG3765		H6500356A01	1	黑皱	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☐ ☐ ☐ ☒
4	DMG4036		5109230	1	灰皱	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☐ ☐ ☐ ☒
5	DMG4037		H2601707A01	2	灰皱	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☐ ☐ ☐
6	DMG4038	无照片	R20410A01	2		确认颜色正确 确认无毛刺 确认无变形 过丝确认	☐ ☐ ☐ ☐
7	DMG4040		5109280	1	灰皱	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☐ ☐ ☐ ☐
8	DMG4041		H2601703A01	2	三价镀锌	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☐ ☐
9	DMG4042		H2601704A01	2	三价镀锌	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☐ ☐ ☐ ☐
10	DMG4043		H2601728A01	1	三价镀锌	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☐ ☒ ☐ ☐
11	DMG4044		H2601729A01	1	三价镀锌	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☐ ☐ ☐ ☒

12	DMG4046		5109243	1	三价镀锌	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒
13	DMG4047		5109276	1	三价镀锌	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒
14	DMG4048		5109277	1	三价镀锌	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒
15	DMG4049		5109278	1	三价镀锌	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒
16	DMG4050		5109272	1	三价镀锌	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒
17	DMG4051		5109268	1	三价镀锌	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒
18	DMG4052		5109273	1	三价镀锌	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒
19	DMG4053		H2601727A01	8	三价镀锌	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒
20	DMG4054		H2601726A01	4	三价镀锌	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒
21	DMG4055		H2602006A02	1	三价镀锌	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒
22	DMG4056		H2601725A01	2	三价镀锌	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒

23	DMG4057		5126759	1	三价镀锌	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒
24	DMG4058		5109283	1	灰皱	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒
25	DMG4059		5127529	1	灰皱	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒
26	DMG4060		5109282	1	灰皱	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒
27	DMG4061		5181909	1	三价镀锌	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒
28	DMG4062		5181986	1	灰皱	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒
29	DMG4063	无简图	R24945A02	4		确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒
30	DMG4066		5147915	1	灰皱	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒
31	DMG4077		H2602001A01	1	黑皱	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒
32	DMG4078		H6500362A01	1	黑皱	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒
33	DMG4083		H2601721A01	1	三价镀锌	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒

34	DMG4085	无简图	5148266	1		确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☐ ☐ ☒
35	DMG4376		5135818	1	灰皱	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☐ ☐ ☒
36	DMG4377		5147910	1	灰皱	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☐ ☐ ☐ ☒
37	DMG4378		H1100637A01	1	黑平	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☐ ☐ ☒
38	DMG4379		H1100638A01	1	黑平	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☐ ☐ ☒
39	DMG4380		H2601737A01	1	灰皱	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☐ ☐ ☒
40	DMG4382		5109241	1	灰皱	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☐ ☒ ☒
41	DMG4462	无简图	5147595	1		确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☐ ☐ ☒
42	DMG4463	无简图	H26530A01	2		确认颜色正确 确认无毛刺 确认无变形 过丝确认	☐ ☐ ☐ ☒
43	DMG4464	无简图	H26702B01	2		确认颜色正确 确认无毛刺 确认无变形 过丝确认	☐ ☐ ☐ ☒
44	DMG5932	无简图	5147564	1		确认颜色正确 确认无毛刺 确认无变形 过丝确认	☐ ☐ ☐ ☒

45	DMG6747		5763050	1	三价镀锌	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒
----	---------	--	---------	---	------	----------------------------------	--