












ALC20260101-02(38批) 本体

序号	T号	型式	简图	数量	颜色	检测内容	备注
1	3	H0104171C01		1	灰皱	①确认颜色正确 ②确认无毛刺	☒ ☒ B组合发货
2	3	H0104370A02		1	灰皱	①确认颜色正确 ②确认无毛刺	☒ ☒ B
3	3	H0504765D01		1	发黑	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒ A
4	3	5385054		1	灰皱	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒ B
5	3	H0104177D03		1	灰皱	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒ 组合发
6	3	H0104354B04		1	灰皱	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒ A装配 组合发 发货
7	3	5504469		1	灰皱	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒ B
8	3	5522363		1	灰皱	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒ A
9	3	5547310		1	灰皱	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒ 装配
10	3	5492858		1	白平	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒ A
11	3	5577663		1	灰皱	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒ A

12	3	5626737		1	白平	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	A
----	---	---------	--	---	----	----------------------------------	--	---