






































PPEXT260501 (2批)

序号	台	ID	简图	数量	颜色	检查内容	工序
1	3	5144685		12	白平	①确认颜色正确 ②确认无毛刺	☒ ☒ ALW
2	3	5144687		1	发黑	①确认颜色正确 ②确认无毛刺	☒ ☒ ALW
3	3	5144699		1	白平	①确认颜色正确 ②确认无毛刺	☒ ☒ ALW
4	3	5144769		1	白皱	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒ ALW
5	3	5144582		22	灰平	①确认颜色正确 ②确认无毛刺	☒ ☒ WSA
6	3	5144840		12	灰平	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒ PPS
7	3	5201102		1	白平	①确认颜色正确 ②确认无毛刺	☒ ☒ ALW
8	3	5201143		1	白平	①确认颜色正确 ②确认无毛刺	☒ ☒ ALW
9	3	5201099		1	发黑	①确认颜色正确 ②确认无毛刺	☒ ☒ ALW
10	3	5201103		1	白平	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒ ALW
11	3	5201105		1	白平	①确认颜色正确 ②确认无毛刺	☒ ☒ ALW

12	3	5201137		1	白皱	①确认颜色正确 ②确认无毛刺	☒ ☒	ALW
13	3	5201138		2	黑平	①确认颜色正确 ②确认无毛刺	☒ ☒	ALW
14	3	5201139		2	黑平	①确认颜色正确 ②确认无毛刺	☒ ☒	ALW
15	3	5201129		1	发黑	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	ALW
16	3	5201130		1	发黑	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	ALW
17	3	5201127		1	白平	①确认颜色正确 ②确认无毛刺	☒ ☒	ALW
18	3	5201128		1	白平	①确认颜色正确 ②确认无毛刺	☒ ☒	ALW
19	3	5201124		4	黄色	①确认颜色正确 ②确认无毛刺	☒ ☒	ALW
20	3	5201140		1	白平	①确认颜色正确 ②确认无毛刺	☒ ☒	ALW
21	3	5201101		1	白平	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	ALW
22	3	5201154		1	白皱	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	ALW

23	3	5201114		1	白平	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	ALW
24	3	5201117		1	白平	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	ALW
25	3	5201149		1	白平	①确认颜色正确 ②确认无毛刺	☒ ☒	ALW
26	3	5201144		1	白平 M10 (细牙 P1.25)	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	ALW
27	3	5201147		1	白平	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	ALW
28	3	5201126		1	黑平	①确认颜色正确 ②确认无毛刺	☒ ☒	ALW
29	3	5201136		1	黑皱	①确认颜色正确 ②确认无毛刺	☒ ☒	ALW
30	3	5201113		1	白平	①确认颜色正确 ②确认无毛刺	☒ ☒	ALW
31	3	5199551		14	灰平	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	PPS
32	3	5200526		8	灰平	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	WSA
33	3	5200528		8	灰平	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	WSA

34	3	5200539		8	灰平	①确认颜色正确 ②确认无毛刺	☐ ☐	WSA
35	3	5144762		1	白皱	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☐ ☒ ☒	ALW
36	3	5144763		1	白皱	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☐ ☒ ☒ ☒	ALW
37	3	5144767		1	发黑	①确认颜色正确 ②确认无毛刺	☒ ☒	ALW
38	3	5144768		1	发黑	①确认颜色正确 ②确认无毛刺	☒ ☒	ALW
39	3	5145093		2	PC板	①确认颜色正确 ②确认无毛刺	☒ ☒	PPS
40	3	5145109		1	白皱	①确认颜色正确 ②确认无毛刺	☒ ☒	PPS
41	3	5226096		2	灰平	①确认颜色正确 ②确认无毛刺	☒ ☐	PPS
42	3	5336177		1	灰平	①确认颜色正确 ②确认无毛刺	☒ ☒	PPS
43	3	5336178		1	灰平	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	PPS
44	3	5358375		1	白皱	①确认颜色正确 ②确认无毛刺	☒ ☒	ALW

45	3	5513103		32	灰平	①确认颜色正确 ②确认无毛刺	☒	WSA
46	3	5607687		1	黄色	①确认颜色正确 ②确认无毛刺	☒	ALW-装配
47	3	5607689		1	黄色	①确认颜色正确 ②确认无毛刺	☒	ALW-装配
48	3	5607685		1	黄色	①确认颜色正确 ②确认无毛刺	☒	ALW
49	3	5608815		1	黄色	①确认颜色正确 ②确认无毛刺	☒	ALW-装配
50	3	5648834		1	白平	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	ALW
51	3	5648835		1	白平	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	ALW
52	3	5648836		1	白平	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	ALW
53	3	5648837		1	白平	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	ALW