















































NHC642300707第四十一批

序号	物料号	内部号	简图	数量	颜色	检查内容	备注
1	H2601638	3722		1	灰皱	确认颜色正确 确认无毛刺 确认无变形 过丝确认	装配
2	H2601638B01(2/4)	#N/A	无图贴在3722柜体上	1	灰皱	①确认颜色正确 ②确认无毛刺	
3	H2601638B01(3/4)	#N/A	无图贴在3722柜体上	1	灰皱	①确认颜色正确 ②确认无毛刺	
4	H2601638B01(4/4)	#N/A	无图贴在3722柜体上	1	灰皱	①确认颜色正确 ②确认无毛刺	
5	H2601853A01	3724	无图贴在3722柜体上	2	灰皱	①确认颜色正确 ②确认无毛刺	
6	H2601795A01A	4086	无图贴在3722柜体上	1	灰皱	①确认颜色正确 ②确认无毛刺	
7	H2601645A02	3725		1	灰皱	①确认颜色正确 ②确认无毛刺	
8	H2601646A02	3726		2	灰皱	①确认颜色正确 ②确认无毛刺	
9	H2601639A03	3727		1	灰皱	①确认颜色正确 ②确认无毛刺	NBR
10	H2B069A01	3728		2	三价镀锌	①确认颜色正确 ②确认无毛刺	

11	H2A959A01	3729		1	三价镀锌	①确认颜色正确 ②确认无毛刺	<input checked="" type="checkbox"/> <input checked="" type="checkbox"/>	
12	H2601782A01	3730		2	三价镀锌	①确认颜色正确 ②确认无毛刺	<input checked="" type="checkbox"/> <input checked="" type="checkbox"/>	
13	H2601169A02	3731		1	三价镀锌	①确认颜色正确 ②确认无毛刺	<input checked="" type="checkbox"/> <input checked="" type="checkbox"/>	发
14	H2601182A02	3732		1	三价镀锌	①确认颜色正确 ②确认无毛刺	<input checked="" type="checkbox"/> <input checked="" type="checkbox"/>	发
15	H2601247A01	3733		1	三价镀锌	①确认颜色正确 ②确认无毛刺	<input checked="" type="checkbox"/> <input checked="" type="checkbox"/>	
16	H2602535A01	3734		1	三价镀锌	①确认颜色正确 ②确认无毛刺	<input checked="" type="checkbox"/> <input checked="" type="checkbox"/>	发
17	H2601788B02	3742		1	三价电镀	①确认颜色正确 ②确认无毛刺	<input checked="" type="checkbox"/> <input checked="" type="checkbox"/>	
18	H2601633A06	3743		1	三价电镀	确认颜色正确 确认无毛刺 确认无变形 过丝确认	<input checked="" type="checkbox"/> <input checked="" type="checkbox"/> <input checked="" type="checkbox"/> <input checked="" type="checkbox"/>	
19	H2601635A04	3744		1	三价电镀	确认颜色正确 确认无毛刺 确认无变形 过丝确认	<input checked="" type="checkbox"/> <input checked="" type="checkbox"/> <input checked="" type="checkbox"/> <input checked="" type="checkbox"/>	
20	H2601636A09	3745		1	三价电镀	确认颜色正确 确认无毛刺 确认无变形 过丝确认	<input checked="" type="checkbox"/> <input checked="" type="checkbox"/> <input checked="" type="checkbox"/> <input checked="" type="checkbox"/>	
21	H2601789A01	3746		1	三价电镀	①确认颜色正确 ②确认无毛刺	<input checked="" type="checkbox"/> <input checked="" type="checkbox"/>	发

22	H2601844B01	3747		1	三阶电镀	①确认颜色正确 ②确认无毛刺	<input checked="" type="checkbox"/>	发
23	H2601637A01	3748		1	三阶电镀	①确认颜色正确 ②确认无毛刺	<input checked="" type="checkbox"/>	
24	H2601654A02	3749		1	灰皱	①确认颜色正确 ②确认无毛刺	<input checked="" type="checkbox"/>	
25	H2601791A01	3750		1	灰皱	①确认颜色正确 ②确认无毛刺	<input checked="" type="checkbox"/>	NBR
26	H2601787A04	3751		1	三阶电镀	确认颜色正确 确认无毛刺 确认无变形 过丝确认	<input checked="" type="checkbox"/>	
27	H2601794A01	3752		1	三阶电镀	确认颜色正确 确认无毛刺 确认无变形 过丝确认	<input checked="" type="checkbox"/>	
28	5180360	3753		1	灰皱	确认颜色正确 确认无毛刺 确认无变形 过丝确认	<input checked="" type="checkbox"/>	
29	H2601666A02	3754		1	灰皱	①确认颜色正确 ②确认无毛刺	<input checked="" type="checkbox"/>	
30	H2601668A03	3755		1	灰皱	确认颜色正确 确认无毛刺 确认无变形 过丝确认	<input checked="" type="checkbox"/>	发
31	5180359	3756		1	灰皱	确认颜色正确 确认无毛刺 确认无变形 过丝确认	<input checked="" type="checkbox"/>	
32	H2601792A02	3757		1	灰皱	确认颜色正确 确认无毛刺 确认无变形 过丝确认	<input checked="" type="checkbox"/>	发

33	H2601955A01	3758		1	灰皱	确认颜色正确 确认无毛刺 确认无变形 过丝确认	<input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	发
34	H2601776A02	3759		1	灰皱	确认颜色正确 确认无毛刺 确认无变形 过丝确认	<input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	发 (装配)
35	H2601777A06	3760		1	黑平	确认颜色正确 确认无毛刺 确认无变形 过丝确认	<input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	发 (装配)
36	H2601898A02	3761		1	黑皱	确认颜色正确 确认无毛刺 确认无变形 过丝确认	<input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	发 (装配)
37	H2602002A02	3762		1	黑皱	①确认颜色正确 ②确认无毛刺	<input type="checkbox"/> <input type="checkbox"/>	发 (装配)
38	H2601900A02	3763		1	黑皱	确认颜色正确 确认无毛刺 确认无变形 过丝确认	<input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	发
39	H6500355A02	3764		1	黑皱	确认颜色正确 确认无毛刺 确认无变形 过丝确认	<input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	发
40	H6500356A01	3765		1	黑皱	①确认颜色正确 ②确认无毛刺	<input type="checkbox"/> <input type="checkbox"/>	发
41	H2601648A04	3768		1	黑皱	确认颜色正确 确认无毛刺 确认无变形 过丝确认	<input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	
42	H2601649A03	3769		1	黑皱	①确认颜色正确 ②确认无毛刺	<input type="checkbox"/> <input type="checkbox"/>	
43	H2601660A03	3801		1	灰皱	确认颜色正确 确认无毛刺 确认无变形 过丝确认	<input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	

44	H8302369B02	3802		1	黑平	确认颜色正确 确认无毛刺 确认无变形 过丝确认	<input checked="" type="checkbox"/> <input checked="" type="checkbox"/> <input checked="" type="checkbox"/> <input checked="" type="checkbox"/>	发
45	H2601793A03	3803		1	三价镀锌	确认颜色正确 确认无毛刺 确认无变形 过丝确认	<input checked="" type="checkbox"/> <input checked="" type="checkbox"/> <input checked="" type="checkbox"/> <input checked="" type="checkbox"/>	
46	H2602016A03	3804		1	三价镀锌	确认颜色正确 确认无毛刺 确认无变形 过丝确认	<input checked="" type="checkbox"/> <input checked="" type="checkbox"/> <input checked="" type="checkbox"/> <input checked="" type="checkbox"/>	
47	H2602018A01	3805		1	灰皱	确认颜色正确 确认无毛刺 确认无变形 过丝确认	<input checked="" type="checkbox"/> <input checked="" type="checkbox"/> <input checked="" type="checkbox"/> <input checked="" type="checkbox"/>	
48	H2601298A01	3808		1	三价镀锌	确认颜色正确 确认无毛刺 确认无变形 过丝确认	<input checked="" type="checkbox"/> <input checked="" type="checkbox"/> <input checked="" type="checkbox"/> <input checked="" type="checkbox"/>	
49	H2601991A01	3806		1	灰皱	确认颜色正确 确认无毛刺 确认无变形 过丝确认	<input checked="" type="checkbox"/> <input checked="" type="checkbox"/> <input checked="" type="checkbox"/> <input checked="" type="checkbox"/>	
50	H2601652A02	4587		1	灰皱	确认颜色正确 确认无毛刺 确认无变形 过丝确认	<input checked="" type="checkbox"/> <input checked="" type="checkbox"/> <input checked="" type="checkbox"/> <input checked="" type="checkbox"/>	
51	H2601657A03	3741		1	灰皱	确认颜色正确 确认无毛刺 确认无变形 过丝确认	<input checked="" type="checkbox"/> <input checked="" type="checkbox"/> <input checked="" type="checkbox"/> <input checked="" type="checkbox"/>	