































NHC20250501 (61批) -先行

序号	台车号	型式	简图	数量	颜色	检测内容	备注
1	1	H0202323A01		1	发黑	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒
2	1	H1405161C02		2	发黑	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒
3	1	H1405614A01		1	发黑	①确认颜色正确 ②确认无毛刺	☒ ☒
4	1	H1405646C02		1	发黑	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒
5	1	H1405655A02		1	发黑	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒
6	1	H1405690A01		2	发黑	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒
7	1	H1405762A03		1	黑平	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒
8	1	H1405764A02		2	发黑	①确认颜色正确 ②确认无毛刺	☒ ☒
9	1	H1406000A01		1	发黑	①确认颜色正确 ②确认无毛刺	☒ ☒
10	1	H1406028B01		1	发黑	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒
11	1	H1605390A02		1	发黑	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒

12	1	H1605493A02		1	白平	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	
13	1	H1605497B03		1	黑平	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	
14	1	H1605631A02		1	黑平	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	
15	1	H3001571A01		1	白平	①确认颜色正确 ②确认无毛刺	☒ ☒	
16	1	H3201777B04		1	灰平	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	
17	1	H8202816B01		1	电镀	①确认颜色正确 ②确认无毛刺	☒ ☒	
18	1	H8202985A02		1	黑平	①确认颜色正确 ②确认无毛刺	☒ ☒	
19	1	H0104507A01		1	黑色	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	
20	1	H1405656B01		1	发黑	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	
21	1	H1405691A05		1	发黑	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	
22	1	H1405763B01		1	发黑	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	

23	1	H1605386B03		1	白平	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	
24	1	5453055		1	黑平	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	
25	1	5457403		1	黑平	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	
26	1	5457404		1	黑平	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	
27	1	5490254		1	黑平	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	
28	1	H1405648A01		1	发黑	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	
29	1	5563855		1	黑色	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	
30	1	5563864		1	黑色	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	
31	1	H3101449C01		1	灰平	①确认颜色正确 ②确认无毛刺	☒ ☒	
32	1	H8202931A01		1	黑平	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	
33	1	5545408		1	黑染	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	