
















NHC5500-散件 (第十五批)

序号	物料号	内部号	简图	数量	颜色	检查内容	备注	A/B等级
1	H8303924C02	3823		1	黑平	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	B
2	H8303927A07	3824		1	黑平	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	B
3	H8303949D01	3827		1	黑平	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	B
4	H8302029C01	3834		1	黑	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	B
5	H8302893A04	3854		1	黑平	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	B
6	H8304114A02	3898		1	黑平	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	B
7	H0400490A03	3909		1	黑平	①确认颜色正确 ②确认无毛刺	☒ ☒	B
8	H0400497A01	3929		2	黑平	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	B
9	H1301189A01	3930		1	黑平(平滑涂装)	①确认颜色正确 ②确认无毛刺	☒ ☒	B
10	H0400489A03	3932		1	黑平	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	B

11	H8303926A03	3933		1	黑平	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒		B
12	H1602582B02	3946		1	黑平	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒		B
13	H47480A01	3947		1	黑平	①确认颜色正确 ②确认无毛刺	☒ ☒		B
14	H1403027A01	3963		1	黑平	①确认颜色正确 ②确认无毛刺	☒ ☒		B
15	H8302030C03	3969		1	黑	①确认颜色正确 ②确认无毛刺	☒ ☒		B
16	H1602583B02	3975		1	黑	①确认颜色正确 ②确认无毛刺	☒ ☒		B
17	H0201565A01	5451		1	发黑	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	测漏	B
18	H0201566A01	5452		1	装配	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	装配	B