
















NHC5500-先行 (第批)

序号	物料号	台车	简图	数量	颜色	检查内容	备注	
1	5313272	2	巴 	1	巴扑	①确认颜色正确 ②确认无毛刺	☒ ☐	B
2	5314391	2	 巴扑	1	巴扑	①确认颜色正确 ②确认无毛刺	☒ ☐	B
3	H8303922A02	2		1	黑	①确认颜色正确 ②确认无毛刺	☒ ☐	B
4	H8304084B03	2		1	灰皱	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	A B
5	H8303944A04	2		1	黑平	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	B
6	H8303940B01	2		1	黑平	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	B
7	H8303941B01	2		1	黑平	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	B
8	H8303992A02	2		1	白皱	①确认颜色正确 ②确认无毛刺	☒ ☒	B
9	H8303933C01	2		1	白皱	①确认颜色正确 ②确认无毛刺	☒ ☐	B
10	H8303932C01	2		1	白皱	①确认颜色正确 ②确认无毛刺	☒ ☒	B

11	H8303925B01	2		1	黑平	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒		B
12	H1403650B02	2		1	黑色	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒		B
13	H8305460A02	2		1	灰皱	①确认颜色正确 ②确认无毛刺	☒ ☒		B
14	H8305461A02	2		1	灰皱	①确认颜色正确 ②确认无毛刺	☒ ☒		B
15	H8305483A01	2		1	白皱	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒		B
16	H8305484A02	2		1	白皱	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒		B
17	H8305485A02	2		1	白皱	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒		B
18	H8305553A01	2		1	白皱	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒		B
19	H8307555A01	2		1	黑色	①确认颜色正确 ②确认无毛刺	☒ ☒		B