















































NHC64250603-0606,0801-0805 901电柜55230502 (9台) (第五批)

序号	物料号	内部号	简图	数量	颜色	检查内容	备注
1	I48699A01D14	4034		1 式	灰皱	确认颜色正确 ☒ 确认无毛刺 ☒ 确认无变形 ☒ 过丝确认 ☒	
	H2601638	3722		1	灰皱	确认颜色正确 ☒ 确认无毛刺 ☒ 确认无变形 ☒ 过丝确认 ☒	
	H2601638B01(2/4)	3722	无图贴在3722柜体上	1	灰皱	①确认颜色正确 ☒ ②确认无毛刺 ☒	
	H2601638B01(3/4)	3722	无图贴在3722柜体上	1	灰皱	①确认颜色正确 ☒ ②确认无毛刺 ☒	
	H2601638B01(4/4)	3722	无图贴在3722柜体上	1	灰皱	①确认颜色正确 ☒ ②确认无毛刺 ☒	
	H2601853A01	3722	无图贴在3722柜体上	2	灰皱	①确认颜色正确 ☒ ②确认无毛刺 ☒	
	H2601795A01A	3722	无图贴在3722柜体上	1	灰皱	①确认颜色正确 ☒ ②确认无毛刺 ☒	
	H2601645A02	3725		1	灰皱	①确认颜色正确 ☒ ②确认无毛刺 ☒	
2	H2601646A02	3726		2	灰皱	①确认颜色正确 ☒ ②确认无毛刺 ☒	
3	H2601639A03	3727		1	灰皱	①确认颜色正确 ☒ ②确认无毛刺 ☒	

4	H2B069A01	3728		2	三价镀锌	①确认颜色正确 ②确认无毛刺	☒ ☒	
5	H2A959A01	3729		1	三价镀锌	①确认颜色正确 ②确认无毛刺	☒ ☒	
6	H2601782A01	3730		2	三价镀锌	①确认颜色正确 ②确认无毛刺	☒ ☒	
7	H2601169A02	3731		1	三价镀锌	①确认颜色正确 ②确认无毛刺	☒ ☒	
8	H2601182A02	3732		1	三价镀锌	①确认颜色正确 ②确认无毛刺	☒ ☒	
9	H2601247A01	3733		1	三价镀锌	①确认颜色正确 ②确认无毛刺	☒ ☒	
10	H2602535A01	3734		1	三价镀锌	①确认颜色正确 ②确认无毛刺	☒ ☒	
11	H2601788B02	3742		1	三价电镀	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	
12	H2601633A06	3743		1	三价电镀	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	
13	H2601635A04	3744		1	三价电镀	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	
14	H2601636A09	3745		1	三价电镀	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	

15	H2601789A01	3746		1	三阶电镀	①确认颜色正确 ②确认无毛刺	☒ ☒	
16	H2601844B01	3747		1	三阶电镀	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	
17	H2601637A01	3748		1	三阶电镀	①确认颜色正确 ②确认无毛刺	☒ ☒	
18	H2601654A02	3749		1	灰皱	①确认颜色正确 ②确认无毛刺	☒ ☒	
19	H2601791A01	3750		1	灰皱	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	
20	H2601787A04	3751		1	三阶电镀	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	
21	H2601794A01	3752		1	三阶电镀	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	
22	5180360	3753		1	灰皱	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	
23	H2601666A02	3754		1	灰皱	①确认颜色正确 ②确认无毛刺	☒ ☒	
24	H2601668A03	3755		1	灰皱	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	
25	5180359	3756		1	灰皱	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	

26	H2601792A02	3757		1	灰皱	①确认颜色正确 ②确认无毛刺	☒ ☒	
27	H2601955A01	3758		1	灰皱	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	
28	H2601431A01	4087		1		确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	
29	H65132D01	4084		1	电镀	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	
30	H2602002A02	3762		1	黑皱	①确认颜色正确 ②确认无毛刺	☒ ☒	
31	H1100576A01	4080		1	会在	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	
32	H2601900A02	3763		1	黑皱	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	
33	H6500355A02	3764		1	黑皱	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	
34	H6500356A01	3765		1	黑皱	①确认颜色正确 ②确认无毛刺	☒ ☒	
35	H2601648A04	3768		1	黑皱	①确认颜色正确 ②确认无毛刺	☒ ☒	
36	H2601649A03	3769		1	黑皱	①确认颜色正确 ②确认无毛刺	☒ ☒	

37	H2601660A03	3801		1	灰皱	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☐ ☒ ☒ ☒	
38	H8302369B02	3802		1	黑平	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	
39	H2601793A03	3803		1	三阶电镀	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	
40	H2602016A03	3804		1	三阶电镀	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☐ ☒ ☒ ☒	
41	H2602018A01	3805		1	灰皱	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☐ ☒ ☒ ☒	
42	H2601991A01	3806		1	灰皱	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	
43	H2601593A01	3807		1	三阶电镀	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☐	
44	H2601467A02	4088		1	三阶电镀	①确认颜色正确 ②确认无毛刺	☐ ☒	
45	H1100577A01	4081		1	灰皱	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	
46	H1100585A02	4082		1	灰皱	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	
47	H2601652A02	4587		1	灰皱	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☐ ☐ ☐ ☐	NBR

48	H2601898A02	3761		1	黑皱	①确认颜色正确 ②确认无毛刺	☐ ☒	
----	-------------	------	---	---	----	-------------------	---	--