




























NHC55250501第五批

序号	物料号	台车号	简图	数量	颜色	检查内容	备注
1	H2601645A02	2		1	灰皱	①确认颜色正确 ②确认无毛刺	☒
2	H2601646A02	2		2	灰皱	①确认颜色正确 ②确认无毛刺	☒
3	H2601639A03	2		1	灰皱	①确认颜色正确 ②确认无毛刺	☒ NBR
4	H2B069A01	2		2	三价镀锌	①确认颜色正确 ②确认无毛刺	☒
5	H2A959A01	2		1	三价镀锌	①确认颜色正确 ②确认无毛刺	☒
6	H2601782A01	2		2	三价镀锌	①确认颜色正确 ②确认无毛刺	☒
7	H2601169A02	2		1	三价镀锌	①确认颜色正确 ②确认无毛刺	☒ 发
8	H2601182A02	2		1	三价镀锌	①确认颜色正确 ②确认无毛刺	☒ 发
9	H2601247A01	2		1	三价镀锌	①确认颜色正确 ②确认无毛刺	☒
10	H2601656A02	2		1	灰皱	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒
11	H2602015A03	2		1	三价镀锌	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒

12	H2602017A01	2		1	灰皱	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	
13	H2601788B02	2		1	三阶电镀	①确认颜色正确 ②确认无毛刺	☒ ☒	
14	H2601633A06	2		1	三阶电镀	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	
15	H2601635A04	2		1	三阶电镀	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	
16	H2601636A09	2		1	三阶电镀	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	
17	H2601637A01	2		1	三阶电镀	①确认颜色正确 ②确认无毛刺	☒ ☒	
18	H2601654A02	2		1	灰皱	①确认颜色正确 ②确认无毛刺	☒ ☒	
19	H2601791A01	2		1	灰皱	①确认颜色正确 ②确认无毛刺	☒ ☒	NBR
20	H2601787A04	2		1	三阶电镀	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	
21	H2601794A01	2		1	三阶电镀	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	
22	5180360	2		1	灰皱	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	

23	H2601668A03	2		1	灰皱	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	发
24	5180359	2		1	灰皱	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	
25	H2601648A04	2		1	黑皱	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	
26	H2601649A03	2		1	黑皱	①确认颜色正确 ②确认无毛刺	☒ ☒	
27	H2601298A01	2		1	黑皱	①确认颜色正确 ②确认无毛刺	☒ ☒	
28	H2601691A02	2		1	三价镀锌	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	发