












































LPP63250801 (20批) - 电柜








序号	内部号	型式	简图	数量	颜色	检测内容	备注
	5608	5624260		1	白皱	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒
	5609	5624261		2	电镀	①确认颜色正确 ②确认无毛刺	☒ ☒
	4399	5624262		1	光泽镀锌	①确认颜色正确 ②确认无毛刺	☒ ☒
	4400	5624263		1	光泽镀锌	①确认颜色正确 ②确认无毛刺	☒ ☒
	4402	5624264		1	光泽镀锌	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒
	5610	5624265		1	白皱	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒
	5611	5624266		1	白皱	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒
	5612	5624267		1	白皱	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒
	4406	5624268		1	光泽镀锌	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒
	4407	5624269		1	光泽镀锌	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒

4408	5624270		1	光泽镀锌	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	
4409	5624271		1	光泽镀锌	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	
4410	5624272		1	光泽镀锌	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	
4411	5624273		1	光泽镀锌	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	
4412	5624274		1	光泽镀锌	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	
4413	5624275		1	光泽镀锌	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	
4415	5624276		1	户内白皱	①确认颜色止确 ②确认无毛刺	☒ ☒	
4416	5624277		1	光泽镀锌	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	
5603387 4417	5624278		1	户内白皱	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	
4418	5624279		1	库存	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	
4419	5501422		6	光泽镀锌	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	

4426	5624280		1	户内白皱	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒
4431	5182787		1	户内白皱	①确认颜色正确 ②确认无毛刺	☒ ☒
4432	5182788		1	户内白皱	①确认颜色正确 ②确认无毛刺	☒ ☒
4414	5629386		1	光泽镀锌	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒
4434	5182790		1	户内白皱	①确认颜色正确 ②确认无毛刺	☒ ☒
4420	5629387		1	户内白皱	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒
4421	5629388		2	光泽镀锌	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒
5616	5624285		1	光泽镀锌	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒
4422	5629389		2	光泽镀锌	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒
4423	5629390		2	光泽镀锌	①确认颜色正确 ②确认无毛刺	☒ ☒
4424	5629391		2	光泽镀锌	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒

4425	5629392		2	户内白皱	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	
5710	5633435		1	光泽镀锌	①确认颜色正确 ②确认无毛刺	☒ ☒	
5711	5633436		1	光泽镀锌	①确认颜色正确 ②确认无毛刺	☒ ☒	
4433	5182789		1	户内白皱	①确认颜色正确 ②确认无毛刺	☒ ☒	
5712	喷胶棉 (550*80*T10)	5629395	1				王震
4435	LPS00A200001C (LPS01A200002B LPS01A200003A)		1	黑皱	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	
4436	LPS00A200009B (LPS01A200008A LPS01A300006 LPS01A300040A)		1	黑皱	①确认颜色正确 ②确认无毛刺	☒ ☒	
4437	LPS01A300007A01		1	黑皱	①确认颜色正确 ②确认无毛刺	☒ ☒	
4438	LPS01A400010A		2	光泽镀锌	①确认颜色正确 ②确认无毛刺	☒ ☒	
4439	LPS01A300013B-1		1	白皱	①确认颜色正确 ②确认无毛刺	☒ ☒	
4441	LPS01A300013B-2		1	白皱	①确认颜色正确 ②确认无毛刺	☒ ☒	

4442	LPS01A300017		1	光泽镀锌	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	
4443	LPS01A300018		1	光泽镀锌	①确认颜色正确 ②确认无毛刺	☒ ☒	
4444	LPS00A200039D (LPS01A200014B LPS00A200039D LPS01A300015A LPS01A300016A LPS01A200019c LPS01A200020B LPS01A200021B)		1	黑皱	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	
4446	LPS00A300024C (LPS01A300022B LPS01A300023 LPS01A300045 LPS01A300046A)		1	黑皱	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	
4447	LPS01A300025A (LPS01A300043)		1	黑皱	①确认颜色正确 ②确认无毛刺	☒ ☒	NBR
4448	LPS01A300026A (LPS01A300044A)		1	黑皱	①确认颜色正确 ②确认无毛刺	☒ ☒	NBR
4449	LPS01A300027C		1	光滑银色	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	
4450	LPS01A300028C		1	黑皱	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	
4451	LPS01A300030		4个件	光泽镀锌	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	组装
4452	LPS01A200031C		1	黑皱	①确认颜色正确 ②确认无毛刺	☒ ☒	
4646	LPS01A200056D		1	光泽镀锌	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	

4454	LPS00A200033B (LPS01A200032A LPS01A300047A)		1	黑皱	①确认颜色正确 ②确认无毛刺	☒ ☒	
4455	LPS00A200037D (LPS01A200034C LPS01A200035)		1	光滑银色	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	
4456	LPS01A300038A		1	光泽镀锌	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	
4457	LPS01A300066		1	光泽镀锌	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	
4458	LPS01A400067		1	光泽镀锌	①确认颜色正确 ②确认无毛刺	☒ ☒	
4459	LPS01A400068		1	光泽镀锌	①确认颜色正确 ②确认无毛刺	☒ ☒	
4460	LPS01A400069		2	黑色	①确认颜色正确 ②确认无毛刺	☒ ☒	
4461	FMS-0501-X364		2	黑色	①确认颜色正确 ②确认无毛刺	☒ ☒	
#N/A	导轨 NS 35		1		王震装配		
5714	导轨 KBR-T2		1		王震装配		
5715	线槽 KL610		1				