





































NHC64230709第二十九批

序号	物料号	内部号	简图	数量	颜色	检查内容	备注
1	H2601638B01	3722		1	灰皱	确认颜色正确 确认无毛刺 确认无变形 过丝确认	装配
2	H2601795A01	3723	无图贴在3722柜体上	1	灰皱	①确认颜色正确 ②确认无毛刺	
3	H2601853A01	3724	无图贴在3722柜体上	2	灰皱	①确认颜色正确 ②确认无毛刺	
4	H2601645A02	3725		1	灰皱	①确认颜色正确 ②确认无毛刺	
5	H2601646A02	3726		2	灰皱	①确认颜色正确 ②确认无毛刺	
6	H2601639A03	3727		1	灰皱	①确认颜色正确 ②确认无毛刺	NBR
7	H2B069A01	3728		2	三价镀锌	①确认颜色正确 ②确认无毛刺	
8	H2A959A01	3729		1	三价镀锌	①确认颜色正确 ②确认无毛刺	
9	H2601782A01	3730		2	三价镀锌	①确认颜色正确 ②确认无毛刺	
10	H2601169A02	3731		1	三价镀锌	①确认颜色正确 ②确认无毛刺	发

11	H2601182A02	3732		1	三价镀锌	①确认颜色正确 ②确认无毛刺	☒	发
12	H2601247A01	3733		1	三价镀锌	①确认颜色正确 ②确认无毛刺	☒	
13	H2602535A01	3734		1	三价镀锌	①确认颜色正确 ②确认无毛刺	☒	发
14	H2601788B02	3742		1	三价电镀	①确认颜色正确 ②确认无毛刺	☒	
15	H2601633A06	3743		1	三价电镀	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	
16	H2601635A04	3744		1	三价电镀	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	
17	H2601636A09	3745		1	三价电镀	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	
18	H2601789A01	3746		1	三价电镀	①确认颜色正确 ②确认无毛刺	☒	发
19	H2601844B01	3747		1	三价电镀	①确认颜色正确 ②确认无毛刺	☒	发
20	H2601637A01	3748		1	三价电镀	①确认颜色正确 ②确认无毛刺	☒	
21	H2601654A02	3749		1	灰皱	①确认颜色正确 ②确认无毛刺	☒	

22	H2601791A01	3750		1	灰皱	①确认颜色正确 ②确认无毛刺	☒	NBR
23	H2601787A04	3751		1	三阶电镀	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☐ ☒ ☒ ☒	
24	H2601794A01	3752		1	三阶电镀	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☐ ☒ ☒ ☒	
25	5180360	3753		1	灰皱	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☐ ☒ ☒ ☒	
26	H2601666A02	3754		1	灰皱	①确认颜色正确 ②确认无毛刺	☒ ☒	
27	H2601668A03	3755		1	灰皱	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☐ ☒ ☒ ☒	发
28	5180359	3756		1	灰皱	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☐ ☒ ☒ ☒	
30	H2601955A01	3758		1	灰皱	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	发
31	H2601776A02	3759		1	灰皱	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	发 (装配)
32	H2601777A06	3760		1	黑平	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	发 (装配)
33	H2601898A02	3761		1	黑皱	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	

34	H2602002A02	3762		1	黑皱	①确认颜色正确 ②确认无毛刺	☒	
35	H2601900A02	3763		1	黑皱	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒	发
36	H6500355A02	3764		1	黑皱	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒	发
37	H6500356A01	3765		1	黑皱	①确认颜色正确 ②确认无毛刺	☒	
38	H2601648A04	3768		1	黑皱	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒	
39	H2601649A03	3769		1	黑皱	①确认颜色正确 ②确认无毛刺	☒	
40	H2601651A02	3800		1	三价镀锌	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒	
41	H2601660A03	3801		1	灰皱	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒	
42	H8302369B02	3802		1	黑平	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒	发
43	H2601793A03	3803		2	三价镀锌	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒	
44	H2602016A03	3804		1	三价镀锌	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒	

45	H2602018A01	3805		1	灰皱	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	
46	H2601991A01	3806		1	灰皱	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	
47	H2601298A01	3808		1	三价镀锌	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	