




































ALC20251103电柜 (第27批)

序号	型式	简图	数量	颜色	检测内容	备注
1	I48750D04 D14		1		①确认颜色正确 ②确认无毛刺	☒ ☒
2	5517549		1	灰皱	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒
3	5517550		1	灰皱	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒
4	5517551		1	灰皱	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒
5	5517955		1	灰皱	①确认颜色正确 ②确认无毛刺	☒ ☒
6	H2B053A02		1	三价镀锌	①确认颜色正确 ②确认无毛刺	☒ ☒
7	5517553		2	灰皱	①确认颜色正确 ②确认无毛刺	☒ ☒
8	H2601611A01		2	灰皱	①确认颜色正确 ②确认无毛刺	☒ ☒
9	5517555		1	灰皱	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒
10	5517556		1	灰皱	①确认颜色正确 ②确认无毛刺	☒ ☒
11	5517559		1	三价镀锌	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒

12	5517561		1	三价镀锌	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	
13	5517562		1	三价镀锌	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	
14	5517563		1	三价镀锌	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	
15	5517564		1	三价镀锌	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	
16	5517565		1	三价镀锌	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	
17	5517566		1	三价镀锌	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	
18	5517567		1	三价镀锌	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	
19	5517568		1	三价镀锌	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	
20	5517569		1	三价镀锌	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	左右各1件
21	5517570		2	三价镀锌	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	
22	H2B050A02		1	三价镀锌	①确认颜色正确 ②确认无毛刺	☒ ☒	

23	5517552		1	三价镀锌	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	
25	H2A901A01		2	三价镀锌	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	NBR
51	H1405660B02		1	黑平	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	
26	5517532		1		确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	
27	5517533	焊在柜上	1		①确认颜色正确 ②确认无毛刺	☒ ☒	
28	5517535	焊在柜上	1		①确认颜色正确 ②确认无毛刺	☒ ☒	
29	5517536	焊在柜上	1		①确认颜色正确 ②确认无毛刺	☒ ☒	
30	5517537	焊在柜上	1		①确认颜色正确 ②确认无毛刺	☒ ☒	
31	5517538	焊在柜上	1		①确认颜色正确 ②确认无毛刺	☒ ☒	
32	5517539	焊在柜上	1		①确认颜色正确 ②确认无毛刺	☒ ☒	
33	5517540	焊在柜上	1		①确认颜色正确 ②确认无毛刺	☒ ☒	

34	5517541	焊在柜上	1		①确认颜色正确 ②确认无毛刺	☒ ☒	
35	5517542	焊在柜上	1		①确认颜色正确 ②确认无毛刺	☒ ☒	
36	5517544	焊在柜上	1		①确认颜色正确 ②确认无毛刺	☒ ☒	
37	5537196	焊在柜上	1		①确认颜色正确 ②确认无毛刺	☒ ☒	
38	5537197	焊在柜上	1		①确认颜色正确 ②确认无毛刺	☒ ☒	
39	5517545	焊在柜上	1		①确认颜色正确 ②确认无毛刺	☒ ☒	
40	5517546	焊在柜上	1		①确认颜色正确 ②确认无毛刺	☒ ☒	
41	5517547	焊在柜上	1		①确认颜色正确 ②确认无毛刺	☒ ☒	
42	5517548	焊在柜上	1		①确认颜色正确 ②确认无毛刺	☒ ☒	
43	5548006		2	灰皱	①确认颜色正确 ②确认无毛刺	☒ ☒	
44	X10334A02		3	R海绵 T	①确认颜色正确 ②确认无毛刺	☒ ☒	

45	X10262A02		2	R海绵 T	①确认颜色正确 ②确认无毛刺	☒ ☒
46	5548892		1	灰皱	①确认颜色正确 ②确认无毛刺	☒ ☒
47	5548895		1	灰皱	①确认颜色正确 ②确认无毛刺	☒ ☒
48	5548884		1	灰皱	①确认颜色正确 ②确认无毛刺	☒ ☒
49	5549869		1	灰皱	①确认颜色正确 ②确认无毛刺	☒ ☒
50	5549870		1	灰皱	①确认颜色正确 ②确认无毛刺	☒ ☒
52	5517581		1	三价镀锌	①确认颜色正确 ②确认无毛刺	☒ ☒
53	5517582		1	灰皱	①确认颜色正确 ②确认无毛刺	☒ ☒
54	5518904		1	灰皱	①确认颜色正确 ②确认无毛刺	☒ ☒
55	B5000281A02		1	黑染	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒