









































电柜NHC81260101第35 批

序号	物料号	内部号	简图	数量	颜色	检查内容	备注
1	H2A959A01	3729		1	三价镀锌	①确认颜色正确 ②确认无毛刺	☒ ☒
2	H2601247A01	3733		1	三价镀锌	①确认颜色正确 ②确认无毛刺	☒ ☒
3	H2601776A02	3759		1	灰皱	①确认颜色正确 ②确认无毛刺	☒ ☒
4	H6500356A01	3765		1	黑皱	①确认颜色正确 ②确认无毛刺	☒ ☒
5	5109230	4036		1	灰皱	①确认颜色正确 ②确认无毛刺	☒ ☒
6	H2601707A01	4037		2	灰皱	①确认颜色正确 ②确认无毛刺	☒ ☒
7	R20410A01	4038		2	0	①确认颜色正确 ②确认无毛刺	☒ ☒
8	5109280	4040		1	灰皱	①确认颜色正确 ②确认无毛刺	☒ ☒
9	H2601703A01	4041		2	三价镀锌	①确认颜色正确 ②确认无毛刺	☒ ☒
10	H2601704A01	4042		2	三价镀锌	①确认颜色正确 ②确认无毛刺	☒ ☒
11	H2601728A01	4043		1	三价镀锌	①确认颜色正确 ②确认无毛刺	☒ ☒

12	H2601729A01	4044		1	三价镀锌	①确认颜色正确 ②确认无毛刺	☒
13	5109243	4046		1	三价镀锌	①确认颜色正确 ②确认无毛刺	☒
14	5109276	4047		1	三价镀锌	①确认颜色正确 ②确认无毛刺	☒
15	5109277	4048		1	三价镀锌	①确认颜色正确 ②确认无毛刺	☒
16	5109278	4049		1	三价镀锌	①确认颜色正确 ②确认无毛刺	☒
17	5109272	4050		1	三价镀锌	①确认颜色正确 ②确认无毛刺	☒
18	5109268	4051		1	三价镀锌	①确认颜色正确 ②确认无毛刺	☒
19	5109273	4052		1	三价镀锌	①确认颜色正确 ②确认无毛刺	☒
20	H2601727A01	4053		8	三价镀锌	①确认颜色正确 ②确认无毛刺	☒
21	H2601726A01	4054		4	三价镀锌	①确认颜色正确 ②确认无毛刺	☒
22	H2602006A02	4055		1	三价镀锌	①确认颜色正确 ②确认无毛刺	☒

23	H2601725A01	4056		2	三价镀锌	①确认颜色正确 ②确认无毛刺	☒ ☒	
24	5126759	4057		1	三价镀锌	①确认颜色正确 ②确认无毛刺	☒ ☒	
25	5109283	4058		1	灰皱	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	
26	5127529	4059		1	灰皱	①确认颜色正确 ②确认无毛刺	☒ ☒	
27	5109282	4060		1	灰皱	①确认颜色正确 ②确认无毛刺	☒ ☒	
28	5181909	4061		1	三价镀锌	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	
29	5181986	4062		1	灰皱	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	
30	R24945A02	4063	门轴	4	0	①确认颜色正确 ②确认无毛刺	☒ ☒	
31	5147915	4066		1	灰皱	①确认颜色正确 ②确认无毛刺	☒ ☒	
32	5147909	4067		1	灰皱	①确认颜色正确 ②确认无毛刺	☒ ☒	
33	H2602258A02	4068		1	灰皱	①确认颜色正确 ②确认无毛刺	☒ ☒	

34	H2602259A04	4069		1	灰皱	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	
35	5153021	4070		1	三价镀锌	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	
51	5152962	4071		1	三价镀锌	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	有票
36	H2602523A01	4072		1	三价镀锌	①确认颜色正确 ②确认无毛刺	☒ ☒	
50	5152982	4073		1	三价镀锌	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	有票
37	5109416	4074		1	三价镀锌	①确认颜色正确 ②确认无毛刺	☒ ☒	
38	H1100613A01	4075		1	黑平	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	
39	H1100614A01	4076		1	黑平	①确认颜色正确 ②确认无毛刺	☒ ☒	
40	H2602001A01	4077		1	黑皱	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	
41	H6500362A01	4078		1	黑皱	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	
42	5148266	4085		1	0	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	

43	5112632	4375		1	黑皱	①确认颜色正确 ②确认无毛刺	☒	
44	5109241	4382		1	灰皱	①确认颜色正确 ②确认无毛刺	☒	
45	5147595	4462	无图贴在4035柜体上	1	0	①确认颜色正确 ②确认无毛刺	☒	
46	H26530A01	4463	部件焊接在柜体上，无需下料	2	0	①确认颜色正确 ②确认无毛刺	☒	
47	H26702B01	4464	焊在箱子上	2	0	①确认颜色正确 ②确认无毛刺	☒	
48	5147564	5932	焊在箱子上	1	0	①确认颜色正确 ②确认无毛刺	☒	
49	A4091	#N/A		1	#N/A	门锁王震别忘了		