



































ALC25260501电柜

序号	内部号	型式	简图	数量	颜色	检测内容	备注
1	4333	5517549		1	内橙色+外指定色	确认颜色正确 确认无毛刺 确认无变形 过丝确认	<input checked="" type="checkbox"/> <input checked="" type="checkbox"/> <input checked="" type="checkbox"/> <input checked="" type="checkbox"/>
2	4334	5517550		1	内橙色+外指定色	确认颜色正确 确认无毛刺 确认无变形 过丝确认	<input checked="" type="checkbox"/> <input checked="" type="checkbox"/> <input checked="" type="checkbox"/> <input checked="" type="checkbox"/>
3	4335	5517551		1	内橙色+外指定色	确认颜色正确 确认无毛刺 确认无变形 过丝确认	<input checked="" type="checkbox"/> <input checked="" type="checkbox"/> <input checked="" type="checkbox"/> <input checked="" type="checkbox"/>
4	4336	5517955		1	指定色	①确认颜色正确 ②确认无毛刺	<input checked="" type="checkbox"/> <input checked="" type="checkbox"/>
5	4338	5517553		2	指定色	①确认颜色正确 ②确认无毛刺	<input checked="" type="checkbox"/> <input checked="" type="checkbox"/>
6	4341	H2601611A01		2	指定色	①确认颜色正确 ②确认无毛刺	<input checked="" type="checkbox"/> <input checked="" type="checkbox"/>
7	4343	5517555		1	橙色	确认颜色正确 确认无毛刺 确认无变形 过丝确认	<input checked="" type="checkbox"/> <input checked="" type="checkbox"/> <input checked="" type="checkbox"/> <input checked="" type="checkbox"/>
8	4344	5517556		1	橙色	①确认颜色正确 ②确认无毛刺	<input checked="" type="checkbox"/> <input checked="" type="checkbox"/>
9	4347	5517559		1	三价镀锌	确认颜色正确 确认无毛刺 确认无变形 过丝确认	<input checked="" type="checkbox"/> <input checked="" type="checkbox"/> <input checked="" type="checkbox"/> <input checked="" type="checkbox"/>
10	4348	5517561		1	三价镀锌	确认颜色正确 确认无毛刺 确认无变形 过丝确认	<input checked="" type="checkbox"/> <input checked="" type="checkbox"/> <input checked="" type="checkbox"/> <input checked="" type="checkbox"/>
11	4349	5517562		1	三价镀锌	确认颜色正确 确认无毛刺 确认无变形 过丝确认	<input checked="" type="checkbox"/> <input checked="" type="checkbox"/> <input checked="" type="checkbox"/> <input checked="" type="checkbox"/>

12	4350	5517563		1	三价镀锌	确认颜色正确 确认无毛刺 确认无变形 过丝确认	<input type="checkbox"/> <input checked="" type="checkbox"/> <input checked="" type="checkbox"/> <input checked="" type="checkbox"/>	
13	4351	5517564		1	三价镀锌	确认颜色正确 确认无毛刺 确认无变形 过丝确认	<input checked="" type="checkbox"/> <input checked="" type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/>	
14	4353	5517565		1	三价镀锌	确认颜色正确 确认无毛刺 确认无变形 过丝确认	<input checked="" type="checkbox"/> <input checked="" type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/>	
15	4354	5517566		1	三价镀锌	确认颜色正确 确认无毛刺 确认无变形 过丝确认	<input checked="" type="checkbox"/> <input checked="" type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/>	
16	4355	5517567		1	三价镀锌	确认颜色正确 确认无毛刺 确认无变形 过丝确认	<input checked="" type="checkbox"/> <input checked="" type="checkbox"/> <input checked="" type="checkbox"/> <input checked="" type="checkbox"/>	
17	4356	5517568		1	三价镀锌	确认颜色正确 确认无毛刺 确认无变形 过丝确认	<input type="checkbox"/> <input checked="" type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/>	
18	4357	5517569		1	三价镀锌	确认颜色正确 确认无毛刺 确认无变形 过丝确认	<input checked="" type="checkbox"/> <input checked="" type="checkbox"/> <input checked="" type="checkbox"/> <input checked="" type="checkbox"/>	右各11
19	4358	5517570		2	三价镀锌	确认颜色正确 确认无毛刺 确认无变形 过丝确认	<input checked="" type="checkbox"/> <input checked="" type="checkbox"/> <input checked="" type="checkbox"/> <input checked="" type="checkbox"/>	
20	4359	H2B050A02		1	三价镀锌	①确认颜色正确 ②确认无毛刺	<input checked="" type="checkbox"/> <input type="checkbox"/>	
21	4360	5517552		1	三价镀锌	确认颜色正确 确认无毛刺 确认无变形 过丝确认	<input checked="" type="checkbox"/> <input checked="" type="checkbox"/> <input checked="" type="checkbox"/> <input checked="" type="checkbox"/>	
22	4361	5517560		1	三价镀锌	①确认颜色正确 ②确认无毛刺	<input checked="" type="checkbox"/> <input type="checkbox"/>	

23	4364	H2A901A01		3	三价镀锌	确认颜色正确 确认无毛刺 确认无变形 过丝确认	<input checked="" type="checkbox"/> <input checked="" type="checkbox"/> <input checked="" type="checkbox"/> <input checked="" type="checkbox"/>	NBR
24	4746	5517532		1	内橙色+外指定色	确认颜色正确 确认无毛刺 确认无变形 过丝确认	<input checked="" type="checkbox"/> <input checked="" type="checkbox"/> <input checked="" type="checkbox"/> <input checked="" type="checkbox"/>	
25	4747	5517533	焊在柜上	1	0	①确认颜色正确 ②确认无毛刺	<input checked="" type="checkbox"/> <input type="checkbox"/>	
26	4748	5517535	焊在柜上	1	0	①确认颜色正确 ②确认无毛刺	<input checked="" type="checkbox"/> <input type="checkbox"/>	
27	4749	5517536	焊在柜上	1	0	①确认颜色正确 ②确认无毛刺	<input checked="" type="checkbox"/> <input type="checkbox"/>	
28	4750	5517537	焊在柜上	1	0	①确认颜色正确 ②确认无毛刺	<input checked="" type="checkbox"/> <input type="checkbox"/>	
29	4751	5517538	焊在柜上	1	0	①确认颜色正确 ②确认无毛刺	<input checked="" type="checkbox"/> <input checked="" type="checkbox"/>	
30	4752	5517539	焊在柜上	1	0	①确认颜色正确 ②确认无毛刺	<input checked="" type="checkbox"/> <input type="checkbox"/>	
31	4753	5517540	焊在柜上	1	0	①确认颜色正确 ②确认无毛刺	<input checked="" type="checkbox"/> <input type="checkbox"/>	
32	4754	5517541	焊在柜上	1	0	①确认颜色正确 ②确认无毛刺	<input checked="" type="checkbox"/> <input type="checkbox"/>	
33	4755	5517542	焊在柜上	1	0	①确认颜色正确 ②确认无毛刺	<input checked="" type="checkbox"/> <input type="checkbox"/>	

34	4756	5517544	焊在柜上	1	0	①确认颜色正确 ②确认无毛刺	<input checked="" type="checkbox"/> <input type="checkbox"/>
35	4757	5537196	焊在柜上	1	0	①确认颜色正确 ②确认无毛刺	<input checked="" type="checkbox"/> <input type="checkbox"/>
36	4758	5537197	焊在柜上	1	0	①确认颜色正确 ②确认无毛刺	<input checked="" type="checkbox"/> <input type="checkbox"/>
37	4759	5517545	焊在柜上	1	0	①确认颜色正确 ②确认无毛刺	<input type="checkbox"/> <input checked="" type="checkbox"/>
38	4760	5517546	焊在柜上	1	0	①确认颜色正确 ②确认无毛刺	<input type="checkbox"/> <input checked="" type="checkbox"/>
39	4761	5517547	焊在柜上	1	0	①确认颜色正确 ②确认无毛刺	<input type="checkbox"/> <input checked="" type="checkbox"/>
40	4762	5517548	焊在柜上	1	0	①确认颜色正确 ②确认无毛刺	<input checked="" type="checkbox"/> <input type="checkbox"/>
41	4763	5548006		2	指定色	①确认颜色正确 ②确认无毛刺	<input checked="" type="checkbox"/> <input type="checkbox"/>
42	4764	X10334A02		3	0	①确认颜色正确 ②确认无毛刺	<input checked="" type="checkbox"/> <input type="checkbox"/>
43	4766	X10262A02		2	0	①确认颜色正确 ②确认无毛刺	<input type="checkbox"/> <input checked="" type="checkbox"/>
44	4767	5548892		1	指定色	①确认颜色正确 ②确认无毛刺	<input type="checkbox"/> <input checked="" type="checkbox"/>

45	4768	5548895		1	指定色	①确认颜色正确 ②确认无毛刺	<input checked="" type="checkbox"/> <input checked="" type="checkbox"/>	
46	4772	5548884		1	指定色	①确认颜色正确 ②确认无毛刺	<input checked="" type="checkbox"/> <input checked="" type="checkbox"/>	
47	4773	5549869		1	指定色	①确认颜色正确 ②确认无毛刺	<input checked="" type="checkbox"/> <input checked="" type="checkbox"/>	
48	4774	5549870		1	橙色	①确认颜色正确 ②确认无毛刺	<input checked="" type="checkbox"/> <input checked="" type="checkbox"/>	
49	5306	H1405997A01		1	指定色	①确认颜色正确 ②确认无毛刺	<input checked="" type="checkbox"/> <input checked="" type="checkbox"/>	装配
50	4765	H2601609A01		1	光泽镀锌	①确认颜色正确 ②确认无毛刺	<input checked="" type="checkbox"/> <input checked="" type="checkbox"/>	
51	5876	H2B053A02		1	光泽镀锌	①确认颜色正确 ②确认无毛刺	<input checked="" type="checkbox"/> <input checked="" type="checkbox"/>	
52	6084	5517577		1	光泽镀锌	确认颜色正确 确认无毛刺 确认无变形 过丝确认	<input checked="" type="checkbox"/> <input checked="" type="checkbox"/> <input checked="" type="checkbox"/> <input checked="" type="checkbox"/>	
53	6085	5517578		1	橙色	确认颜色正确 确认无毛刺 确认无变形 过丝确认	<input checked="" type="checkbox"/> <input checked="" type="checkbox"/> <input checked="" type="checkbox"/> <input checked="" type="checkbox"/>	
54	6086	5518902		1	橙色	确认颜色正确 确认无毛刺 确认无变形 过丝确认	<input checked="" type="checkbox"/> <input checked="" type="checkbox"/> <input checked="" type="checkbox"/> <input checked="" type="checkbox"/>	装配