






























ALC25251102 (33批) - 先行

序号	T号	型式	简图	数量	颜色	检测内容	备注
1	1	H0202323A01		1	发黑	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒
2	1	H1405161C02		2	发黑	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒
3	1	H1405614A01		1	发黑	①确认颜色正确 ②确认无毛刺	☒ ☒
4	1	H1406028B01		1	发黑	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒
5	1	H1605390A02		1	发黑	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒
6	1	H1605493A02		1	白平	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒
7	1	H1605497B03		1	黑平	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒
8	1	H1605631A02		1	黑平	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒
9	1	H8202816B01		1	铬酸盐	①确认颜色正确 ②确认无毛刺	☒ ☒
10	1	H8202985A02		1	黑平	①确认颜色正确 ②确认无毛刺	☒ ☒

11	1	B6803172A01		1	黑平	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☐ ☐ ☐	
12	1	H1405611A01		1	发黑	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☐ ☒ ☒ ☐	
13	1	H1405631C02		1	发黑	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☐ ☐ ☒ ☐	
14	1	H1405932A01		1	黑平	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☐ ☒ ☒ ☐ ☒	装配
15	1	H1605618B01		1	白皱	①确认颜色正确 ②确认无毛刺	☒ ☐	
16	1	H3001301A02		1	黑平	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☐	
17	1	H1405617B01		1	黑平	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☐ ☐ ☒ ☐	
18	1	5418295		1	黑平	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☐ ☐	
19	1	H0104507A01		1	黑平	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☐ ☐ ☒ ☐	
20	1	5453055		1	黑平	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☐ ☒ ☒ ☒ ☐	
21	1	5493083		1	灰平	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☐ ☐ ☒ ☐ ☒	

22	1	H1405612A02		3	发黑	①确认颜色正确 ②确认无毛刺	☒ ☒	
23	1	H1405615C01		1	发黑	①确认颜色正确 ②确认无毛刺	☒ ☒	
24	1	H1405616B04		1	发黑	①确认颜色正确 ②确认无毛刺	☒ ☒	
25	1	H1405994A01		1	黑平	①确认颜色正确 ②确认无毛刺	☒ ☒	
26	1	5457700		1	黑平	①确认颜色正确 ②确认无毛刺	☒ ☒	
27	1	5457701		1	黑平	①确认颜色正确 ②确认无毛刺	☒ ☒	
28	1	5490255		1	黑平	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	
29	1	5563855		1	黑平	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	
30	1	5563864		1	黑平	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	
31	1	5545408		1	发黑	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	