











序号	内部号	小图	物料名称	数量	颜色	检查内容	备注
1	1		H0703552A01	1	灰皱	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒
2	1		H1H351A06	1	黑平	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒
3	1		H0703753B01	1	灰皱	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒ 打胶组合
4	1		H0703826A01	1	灰皱	①确认颜色正确 ②确认无毛刺	☒ ☒
5	1		H8305274A02	1	灰皱	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒
6	1		H8305300A01	1	灰皱	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒ 装配发货
7	1		H8305850A01	1	灰皱	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒
8	1		H8306376A01	1	灰皱	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒
9	1		H8306377A01	1	灰皱	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒
10	1		H8306379A01	1	灰皱	①确认颜色正确 ②确认无毛刺	☒ ☒ 组合发货

11	1		5310568	1	灰皱	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	
----	---	--	---------	---	----	----------------------------------	--	--