









序号	内部号	小图	物料名称	数量	颜色	检查内容	备注
1	4		5149955	1	灰皱	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒
2	4		H0703351A01	1	灰皱	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒ 打胶
3	4		H0703352A01	1	灰皱	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒ 装配
4	4		H0703750A02	1	灰皱	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒ 打胶
5	4		H0703825A01	1	灰皱	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒
6	4		H8305277A01	1	灰皱	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒
7	4		H8305301A01	3	灰皱	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒
8	4		H8305302A01	2	灰皱	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒
9	4		H8305303A01	1	灰皱	①确认颜色正确 ②确认无毛刺	☒ ☒
10	4		H8305305A01	1	灰皱	①确认颜色正确 ②确认无毛刺	☒ ☒

11	4		5424777	1	灰皱	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	装配发货
----	---	--	---------	---	----	----------------------------------	--	------