


















NHC81261002-1CQ (11批)

序	台车	小图	物料名称	数量	颜色	检查内容	备注
1	1		H0703574A	2	黑平	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒
2	1		H1301780A	1	灰皱	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒
2	1		H1403180A	1	黑平	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒
3	1		H1604036A	1	黑平	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒
3	1		H1604037A	1	黑平	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒
4	1		H1604257A	1	黑平	①确认颜色正确 ②确认无毛刺	☒ ☒
4	1		H1604258A	1	黑平	①确认颜色正确 ②确认无毛刺	☒ ☒
5	1		H1604259A	1	黑平	①确认颜色正确 ②确认无毛刺	☒ ☒
5	1		H1604260C	1	黑平	①确认颜色正确 ②确认无毛刺	☒ ☒
6	1		H1604261A	1	黑平	①确认颜色正确 ②确认无毛刺	☒ ☒

6	1		H1604262A	1	黑平	①确认颜色正确 ②确认无毛刺	☒ ☒	
7	1		H1G371A01	1	黑平	①确认颜色正确 ②确认无毛刺	☒ ☒	
7	1		H1G372A01	1	黑平	①确认颜色正确 ②确认无毛刺	☒ ☒	
8	1		H47690A01	1	黑平	①确认颜色正确 ②确认无毛刺	☒ ☒	
8	1		H47722A02	1	黑平	①确认颜色正确 ②确认无毛刺	☒ ☒	
9	1		H47723A01	1	黑平	①确认颜色正确 ②确认无毛刺	☒ ☒	
9	1		H8305271B	1	灰皱	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	