

































LPP63251201 (37批)






A2A	台车号	型式	简图	数量	颜色		备注	台车位置
1	2	5144864		2	白皱	①确认颜色正确 ②确认无毛刺	☒ ☒	LDA 3层台车 →最上面
2	2	5144865		1	灰平	①确认颜色正确 ②确认无毛刺	☒ ☒	LDA 3层台车 →最上面
3	2	5144867		1	灰平	①确认颜色正确 ②确认无毛刺	☒ ☒	LDA 3层台车 →最上面
4	2	5144881		1	灰平	①确认颜色正确 ②确认无毛刺	☒ ☒	LDA 3层台车 →最上面
5	2	5144882		1	灰平	①确认颜色正确 ②确认无毛刺	☒ ☒	LDA 3层台车 →最上面
6	2	5144898		10	灰平	①确认颜色正确 ②确认无毛刺	☒ ☒	LCA 3层台车 →最上面
7	2	5144899		10	灰平	①确认颜色正确 ②确认无毛刺	☒ ☒	LCA 3层台车 →最上面
8	2	5144895		2	白平	①确认颜色正确 ②确认无毛刺	☒ ☒	LCA 3层台车 →最上面
9	2	5144896		1	灰平	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	LCA 3层台车 →最上面
10	2	5144866		1	灰平	①确认颜色正确 ②确认无毛刺	☒ ☒	LDA 3层台车 →最上面

11	2	5145105		1	白皱	①确认颜色正确 ②确认无毛刺	☒ ☐	LCO	3层台车 →最上面
12	2	5144903		1	灰平	①确认颜色正确 ②确认无毛刺	☒ ☒	LCA	3层台车 →最上面
13	2	5145110		1	白皱	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	ALW	3层台车 →下
14	2	5237759		1	灰平	①确认颜色正确 ②确认无毛刺	☒ ☒	AXL	3层台车 →最下面
15	2	5144791		4	黑平	①确认颜色正确 ②确认无毛刺	☒ ☒	ALW	3层台车 →最中面
16	2	5144792		4	黑平	①确认颜色正确 ②确认无毛刺	☒ ☒	ALW	3层台车 →最中面
17	2	5144909	 メーカ: 型式:	1	灰平	①确认颜色正确 ②确认无毛刺	☒ ☒	LCA	3层台车 →最中面
18	2	5144904		1	灰平	①确认颜色正确 ②确认无毛刺	☒ ☒	LCA	3层台车 →最中面
19	2	5144876		4	0	①确认颜色正确 ②确认无毛刺	☒ ☒	LDA	三层台车 →最上面
20	2	5144877		6	0	①确认颜色正确 ②确认无毛刺	☒ ☒	LDA	三层台车 →最上面
21	2	5144044		1	灰平	①确认颜色正确 ②确认无毛刺	☒ ☒	AXL	三层台车 →最中面

22	2	5144019		2	灰平	①确认颜色正确 ②确认无毛刺	☒ ☒	AXL	三层台车 →最中面
23	2	5144033		1	灰平	①确认颜色正确 ②确认无毛刺	☒ ☒	AXL	三层台车 →最中面
24	2	5144072		1	灰平	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	AYL	三层台车 →最中面
25	2	5144080		1	灰平	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	AYL	三层台车 →最中面
26	2	5144538		1	灰平	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	AZL	三层台车 →最中面
27	2	5144539		1	灰平	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	AZL	三层台车 →最中面
28	2	5144540		1	灰平	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	AZL	三层台车 →最中面
29	2	5144541		1	灰平	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	AZL	三层台车 →最中面
30	2	5144543		1	灰平	①确认颜色正确 ②确认无毛刺	☒ ☒	AZL	三层台车 →最中面
31	2	5144544		2	灰平	①确认颜色正确 ②确认无毛刺	☒ ☒	AZL	三层台车 →最中面
32	2	5144546		1	灰平	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	AZL	三层台车 →最中面

33	2	5144547		1	灰平	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	AZL	三层台车 →最中面
34	2	5144548		2	灰平	①确认颜色正确 ②确认无毛刺	☒ ☒	AZL	三层台车 →最中面
35	2	5144550		1	灰平	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	AZL	三层台车 →最上面
36	2	5298971		3	0	①确认颜色正确 ②确认无毛刺	☒ ☒	AZL	三层台车 →最中面
37	2	5144553		2	0	①确认颜色正确 ②确认无毛刺	☒ ☒	AZL	三层台车 →最中面
38	2	5144555		1	灰平	①确认颜色正确 ②确认无毛刺	☒ ☒	AZL	三层台车 →最中面
39	2	5144556		20	样板 61024 37YB T2.0	①确认颜色正确 ②确认无毛刺	☒ ☒	AZL	三层台车 →最中面
40	2	5144558		1	灰平	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	AZL	三层台车 →最中面
41	2	5144559		1	灰平	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	AZL	三层台车 →最中面
42	2	5144083		1	灰平	①确认颜色正确 ②确认无毛刺	☒ ☒	AYL	三层台车 →最中面
43	2	5237729		1	灰平	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	AZL	三层台车 →最中面

44	2	5237730		1	灰平	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	AZL	三层台车 →最中面
45	2	5298968		2	灰平	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	AXL	三层台车 →最中面
46	2	5298970		1	灰平	①确认颜色正确 ②确认无毛刺	☒ ☒	AZL	三层台车 →最中面
47	2	5607698		1	灰平	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	AXL	三层台车 →最中面
48	2	5144897		2	灰平	①确认颜色正确 ②确认无毛刺	☒ ☒	LCA	三层台车 →最上面
49	2	5144842		4	黑皱	①确认颜色正确 ②确认无毛刺	☒ ☒	LCA	组装
50	2	5144908		1	灰平	①确认颜色正确 ②确认无毛刺	☒ ☒	LCA	3上
51	2	5144910		17	灰平	①确认颜色正确 ②确认无毛刺	☒ ☒	LCA	3上
52	2	5144883		18	白皱	①确认颜色正确 ②确认无毛刺	☒ ☒	LCA	3下
53	2	5144840		20	灰平	①确认颜色正确 ②确认无毛刺	☒ ☒	LDA	3下
54	2	5145131		2	黄色	①确认颜色正确 ②确认无毛刺	☒ ☒	SPP	3下

55	2	5144077		2	黄色	①确认颜色正确 ②确认无毛刺	☒ ☒	AYL	3下
56	2	5144042		2	黄色	①确认颜色正确 ②确认无毛刺	☒ ☒	AXL	3下
57	2	5144047		1	黄色	①确认颜色正确 ②确认无毛刺	☒ ☒	AXL	3下
58	2	5513103		52	灰平	①确认颜色正确 ②确认无毛刺	☒ ☒	WSA	3下
59	2	5607689		2	黄色	①确认颜色正确 ②确认无毛刺	☒ ☒	ALW	3下
60	2	5607691		2	黄色	①确认颜色正确 ②确认无毛刺	☒ ☒	ALW	3下
61	2	5607693		2	黄色	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	ALW	3下
62	2	5607705		2	黄色	①确认颜色正确 ②确认无毛刺	☒ ☒	ALW	3下