

























ALC25250501-0502(61批) 本体

序号	台车号	型式	简图	数量	颜色	检测内容	备注
1	2	5413214		1	白平	①确认颜色正确 ②确认无毛刺	☒ ☒
2	2	H0004079A01		1	黑平	①确认颜色正确 ②确认无毛刺	☒ ☒
3	2	H0104369A01		1	灰皱	①确认颜色正确 ②确认无毛刺	☒ ☒
4	2	H0504769A03		1	黑色	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒
5	2	H0504770A01		1	黑色	①确认颜色正确 ②确认无毛刺	☒ ☒
6	2	H1503061A01		1	黑平	①确认颜色正确 ②确认无毛刺	☒ ☒
7	2	H1605084A01		1	黑平	①确认颜色正确 ②确认无毛刺	☒ ☒
8	2	H1605384A01		1	白平	①确认颜色正确 ②确认无毛刺	☒ ☒
9	2	H1605388B02		1	白平	①确认颜色正确 ②确认无毛刺	☒ ☒
10	2	H3101443A01		1	白皱	①确认颜色正确 ②确认无毛刺	☒ ☒

11	2	5362501		1	白皱	①确认颜色正确 ②确认无毛刺	☒ ☒	
12	2	5362505		1	白皱	①确认颜色正确 ②确认无毛刺	☒ ☒	
13	2	5362592		1	白皱	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	
14	2	5385041		3	灰皱	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	
15	2	H1605632A01		1	白平	①确认颜色正确 ②确认无毛刺	☒ ☒	
16	2	H3001577A01		2	黑皱	①确认颜色正确 ②确认无毛刺	☒ ☒	
17	2	H1605648A02		1	灰皱	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	
18	2	H6500383A02		1	黑皱	①确认颜色正确 ②确认无毛刺	☒ ☒	
19	2	H8202881B01		1	白皱	①确认颜色正确 ②确认无毛刺	☒ ☒	组合发货
20	2	5461795		1	黑皱	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	

21	2	5461796		1	黑皱	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☐ ☐ ☒	
22	2	5525795		1	灰皱	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☐ ☐ ☐	
23	2	5547310		1	灰皱	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☐ ☒ ☒	装配
24	2	H0504843B01		1	灰皱	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☐ ☐ ☐	
25	2	5406535		1	发丝件	①确认颜色正确 ②确认无毛刺	☒ ☒	
26	2	H8202904A01		1	黑平	①确认颜色正确 ②确认无毛刺	☒ ☒	