


















LPP40250101(四十六批)

序号	台车号	型式	简图	数量	颜色	检查内容	工序
1	1	5144862		1	黑皱	①确认颜色正确 ②确认无毛刺	☒ ☒ LDA
2	1	5144876		4		①确认颜色正确 ②确认无毛刺	☒ ☒ LDA
3	1	5144877		6		确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒ LDA
4	1	5145096		1	白皱	①确认颜色正确 ②确认无毛刺	☒ ☒ LCO
5	1	5145097		1	白皱	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒ LCO
6	1	5145098		2	白皱	①确认颜色正确 ②确认无毛刺	☒ ☒ LCO
7	1	5145099		1	白皱	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒ LCO
8	1	5145100		1	白皱	①确认颜色正确 ②确认无毛刺	☒ ☒ LCO
9	1	5145101		1	白皱	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒ LCO
10	1	5145103		1	白皱	①确认颜色正确 ②确认无毛刺	☒ ☒ LCO

11	1	5145105		1	白皱	①确认颜色正确 ②确认无毛刺	☒ ☒	LCO
12	1	5145106		2	白皱	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	LCO
13	1	5199297		1	灰平	①确认颜色正确 ②确认无毛刺	☒ ☒	LDA
14	1	5199298		1	灰平	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	LDA
15	1	5200508		1	灰平	①确认颜色正确 ②确认无毛刺	☒ ☒	AZL
16	1	5200509		1	灰平	①确认颜色正确 ②确认无毛刺	☒ ☒	AZL
17	1	5384800		1	灰平	①确认颜色正确 ②确认无毛刺	☒ ☒	AZL
18	1	5384802		1	灰平	①确认颜色正确 ②确认无毛刺	☒ ☒	AZL
19	1	5384803		1	灰平	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	AZL
20	1	5384805		1	灰平	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	AZL
21	1	5384807		1	灰平	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	AZL

22	1	5384809		1	灰平	①确认颜色正确 ②确认无毛刺	☒ ☒	AZL
23	1	5384812		1	灰平	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	AZL
24	1	5384813		1	灰平	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	AZL
25	1	5384814		1	灰平	①确认颜色正确 ②确认无毛刺	☒ ☒	AZL
26	1	5384817		1	灰平	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	AZL