


















LPP40250101

序号	订单	台车号	简图	数量	颜色	检查内容		
1	5201124	1		4	黄色	①确认颜色正确 ②确认无毛刺	☒ ☒	ALW
2	5519534	1		2	黄色	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	SPP
3	5519536	1		4	黄色	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	SPP
4	5519571	1		1	灰平	①确认颜色正确 ②确认无毛刺	☒ ☒	SPP
5	5519574	1		2	黄色	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	SPP
6	5519576	1		2	黄色	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	SPP
7	5519581	1		4	黄色	①确认颜色正确 ②确认无毛刺	☒ ☒	SPP
8	5549910	1		1	黄色	①确认颜色正确 ②确认无毛刺	☒ ☒	ALW
9	5386352	1		1		①确认颜色正确 ②确认无毛刺	☒ ☒	PBP
10	5386353	1		1	电镀	①确认颜色正确 ②确认无毛刺	☒ ☒	PBP
11	5386354	1		1	电镀	①确认颜色正确 ②确认无毛刺	☒ ☒	PBP

12	5386345	1		1	白皱	①确认颜色正确 ②确认无毛刺	☒ ☒	PBP
13	5386346	1		1	白皱	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	PBP
14	5386349	1		1	光泽镀锌	①确认颜色正确 ②确认无毛刺	☒ ☒	PBP
15	5615670	1		3	黄色	①确认颜色正确 ②确认无毛刺	☒ ☒	SPP
16	5615671	1		1	黄色	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	SPP
17	5615672	1		2	黄色	①确认颜色正确 ②确认无毛刺	☒ ☒	SPP
18	5617367	1		1	光泽镀锌	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	PBP
19	5607687	1		2	黄色	①确认颜色正确 ②确认无毛刺	☒ ☒	装配ALW
20	5607689	1		2	黄色	①确认颜色正确 ②确认无毛刺	☒ ☒	ALW
21	5618008	1		4	黄色	①确认颜色正确 ②确认无毛刺	☒ ☒	SPP
22	5618612	1		2	黄色	①确认颜色正确 ②确认无毛刺	☒ ☒	ALW

23	5618613	1		2	黄色	①确认颜色正确 ②确认无毛刺		ALW
----	---------	---	--	---	----	-------------------	---	-----