


















LPP50250801 (二十一 批)

序号	台车号	ID	简图	数量	颜色	检查内容	工序
1	1	5145098		2	白皱	①确认颜色正确 ②确认无毛刺	☒ ☒ LCO
2	1	5145105		1	白皱	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒ LCO
3	1	5145096		1	白皱	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒ LCO
4	1	5145097		1	白皱	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒ LCO
5	1	5145099		1	白皱	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒ LCO
6	1	5145100		1	白皱	①确认颜色正确 ②确认无毛刺	☒ ☒ LCO
7	1	5145101		1	白皱	①确认颜色正确 ②确认无毛刺	☒ ☒ LCO
8	1	5145106		2	白皱	①确认颜色正确 ②确认无毛刺	☒ ☒ LCO
9	1	5200501		1	灰平	①确认颜色正确 ②确认无毛刺	☒ ☒ AZL
10	1	5200508		1	灰平	①确认颜色正确 ②确认无毛刺	☒ ☒ AZL
11	1	5200509		1	灰平	①确认颜色正确 ②确认无毛刺	☒ ☒ AZL

12	1	5200513		1	灰平	①确认颜色正确 ②确认无毛刺	☒ ☒	AZL
13	1	5200500		1	灰平	①确认颜色正确 ②确认无毛刺	☒ ☒	AZL
14	1	5200502		1	灰平	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	AZL
15	1	5200503		1	灰平	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	AZL
16	1	5200506		1	灰平	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	AZL
17	1	5200507		2	黄色	①确认颜色正确 ②确认无毛刺	☒ ☒	AZL
18	1	5200510		1	灰平	①确认颜色正确 ②确认无毛刺	☒ ☒	AZL
19	1	5365119		1	灰平	①确认颜色正确 ②确认无毛刺	☒ ☒	AZL
20	1	5365118		1	灰平	①确认颜色正确 ②确认无毛刺	☒ ☒	AZL
21	1	5513117		1	灰平	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	AZL