








LPP50250701 (二十一一批)

序号	台车号	ID	简图	数量	颜色	检查内容	工序
1	5	5201112		2	白皱	确认颜色正确 确认无毛刺 确认无变形 过丝确认	ALW
2	5	5201107		1	白皱	确认颜色正确 确认无毛刺 确认无变形 过丝确认	ALW
3	5	5201108		1	白皱	专人检查	ALW
4	5	5201133		2	黑皱	①确认颜色正确 ②确认无毛刺	ALW
5	5	5201134		2	黑皱	①确认颜色正确 ②确认无毛刺	ALW
6	5	5201135		2	黑皱	①确认颜色正确 ②确认无毛刺	ALW
7	5	5403788		2	白皱	①确认颜色正确 ②确认无毛刺	ALW
8	5	5403791		2	白皱	①确认颜色正确 ②确认无毛刺	ALW
9	5	5607684		2	白皱	确认颜色正确 确认无毛刺 确认无变形 过丝确认	ALW
10	5	5607686		2	白皱	确认颜色正确 确认无毛刺 确认无变形 过丝确认	ALW
11	5	5607688		2	黑皱	①确认颜色正确 ②确认无毛刺	ALW

12	5	5607690		2	白皱	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	ALW
----	---	---------	--	---	----	----------------------------------	--	-----