








LPP50250701 (二十一 批)

序号	台车号	ID	简图	数量	颜色	检查内容	工序
1	2	5201086		2	白平	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒ ALW
2	2	5365131		2	白平	①确认颜色正确 ②确认无毛刺	☒ ☒ ALW
3	2	5365132		2	白平	①确认颜色正确 ②确认无毛刺	☒ ☒ ALW
4	2	5201148		2	白平	①确认颜色正确 ②确认无毛刺	☒ ☒ ALW
5	2	5201104		2	白平	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒ ALW
6	2	5201118		2	白皱	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒ ALW
7	2	5201119		2	白皱	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒ ALW
8	2	5201120		2	白皱	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒ ALW
9	2	5201121		2	白皱	①确认颜色正确 ②确认无毛刺	☒ ☒ ALW
10	2	5201122		2	白皱	①确认颜色正确 ②确认无毛刺	☒ ☒ ALW

11	2	5365130		2	白平	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	ALW
12	2	5201107		1	白皱	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	ALW
13	2	5201108		1	白皱	专大检查		ALW