














LPP80251001第25批

序号	物料号	台车号	简图	数量	颜色	检查内容	备注
1	5197099	4		1	灰平	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒ AYL
2	5197238	4		4	白皱	①确认颜色正确 ②确认无毛刺	☒ ☒ ALW
3	5197239	4		4	白皱	①确认颜色正确 ②确认无毛刺	☒ ☒ ALW
4	5197306	4		2	白平	①确认颜色正确 ②确认无毛刺	☒ ☒ ALW
5	5197346	4		2	白平	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒ ALW
6	5197347	4		2	白皱	①确认颜色正确 ②确认无毛刺	☒ ☒ ALW
7	5197352	4		2	白皱	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒ ALW
8	5197361	4		2	黑平	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒ ALW
9	5197406	4		4	白皱	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒ ALW
10	5197417	4		2	白皱	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒ ALW
11	5197418	4		2	白皱	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒ ALW

12	5197419	4		2	白皱	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	ALW
13	5197420	4		2	白皱	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	ALW
14	5197421	4		2	白皱	①确认颜色正确 ②确认无毛刺	☒ ☒	ALW
15	5197422	4		2	白皱	①确认颜色正确 ②确认无毛刺	☒ ☒	ALW
16	5197423	4		2	白皱	①确认颜色正确 ②确认无毛刺	☒ ☒	ALW
17	5197438	4		2	白平	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	ALW
18	5614801	4		2	白皱	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	ALW