






















ALC25251001-1101(33批) 本体

序号	台车号	型式	简图	数量	颜色	检测内容	备注
1	2	5413214		1	白平	①确认颜色正确 ②确认无毛刺	☒ ☒ B
2	2	5413820		1	灰平	①确认颜色正确 ②确认无毛刺	☒ ☒ B
3	2	H0004079A01		1	黑平	①确认颜色正确 ②确认无毛刺	☒ ☒ B
4	2	H0104296B01		1	灰皱	①确认颜色正确 ②确认无毛刺	☒ ☒ B
5	2	H0104343A01		1	灰皱	①确认颜色正确 ②确认无毛刺	☒ ☒ B
6	2	H0504731B02		1	白平	①确认颜色正确 ②确认无毛刺	☒ ☒ B
7	2	H0504732A02		1	黑色	①确认颜色正确 ②确认无毛刺	☒ ☒ B
8	2	H0504769A03		1	黑色	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒ B
9	2	H0504770A01		1	黑色	①确认颜色正确 ②确认无毛刺	☒ ☒ B
10	2	H0504920A03		1	灰皱	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒ A

11	2	H1502976B01		1	白平	①确认颜色正确 ②确认无毛刺	☒	B
12	2	H1502999A01		1	灰皱		☒	
13	2	H1503061A01		1	黑平	①确认颜色正确 ②确认无毛刺	☒	B
14	2	H1604995A04		1	灰皱	①确认颜色正确 ②确认无毛刺	☒	B
15	2	H1605084A01		1	黑平	①确认颜色正确 ②确认无毛刺	☒	B
16	2	H1605378B01		1	白平	①确认颜色正确 ②确认无毛刺	☒	A
17	2	H1605384A01		1	白平	①确认颜色正确 ②确认无毛刺	☒	A
18	2	H1605420A02		1	黑平	①确认颜色正确 ②确认无毛刺	☒	B
19	2	H1605421A01		1	黑平	①确认颜色正确 ②确认无毛刺	☒	B
20	2	H1605682A01		1	白平	①确认颜色正确 ②确认无毛刺	☒	B
21	2	H3001539A02		1	黑平	①确认颜色正确 ②确认无毛刺	☒	B

22	2	H3001586A01		1	黑平	①确认颜色正确 ②确认无毛刺	☒ ☒	B
23	2	H3101443A01		1	白皱	①确认颜色正确 ②确认无毛刺	☒ ☒	B
24	2	H3201831A01		1	黑平	①确认颜色正确 ②确认无毛刺	☒ ☒	B
25	2	H3201811A02		1	白平	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	A
26	2	H3201812B01		1	白平	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	A
27	2	H8202986B01		1	白平	①确认颜色正确 ②确认无毛刺	☒ ☒	A
28	2	5524456		1	白皱	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	A
29	2	5577901		1	灰皱	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	A