











ALC20251103本体 (33批)

序号	台车号	型式	简图	数量	颜色	检测内容	备注	
1	3	H1605384A01		1	白平	①确认颜色正确 ②确认无毛刺	☒	
2	3	H3201809B02		1	白平	①确认颜色正确 ②确认无毛刺	☒	
3	3	H3201810B03		1	白平	①确认颜色正确 ②确认无毛刺	☒	
4	3	H0504856B02		1	白平	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	
5	3	H0504864D01		1	白平	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	
6	3	H6500383A02		1	黑皱	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	
7	3	H0504851C01		1	白平	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	组合发
8	3	H0504862E01		1	白平	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	组合发
9	3	H1603639A02		1	灰皱	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	
10	3	H8202978A01		1	灰皱	①确认颜色正确 ②确认无毛刺	☒ ☒	

11	3	H8202979A02		1	灰皱	①确认颜色正确 ②确认无毛刺		
----	---	-------------	--	---	----	-------------------	---	--