





LPP50251201 (34批)

序号	台车号	ID	简图	数量	颜色	检查内容	工序	
1	6	5144836		5	黑皱	①确认颜色正确 ②确认无毛刺	☒ ☒	LCA
2	6	5144842		4	黑皱	①确认颜色正确 ②确认无毛刺	☒ ☒	LCA
3	6	5144885		1	白皱	①确认颜色正确 ②确认无毛刺	☒ ☒	LCA
4	6	5144886		11	白皱	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	LCA
5	6	5199536		1	白皱	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	
6	6	5199538		1	白皱	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	LCA
7	6	5199540		3	白皱	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	LCA
8	6	5199542		4	白皱	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	LCA
9	6	5636570		1	白皱	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	