











LPP50251201 (34批)

序号	台车号	ID	简图	数量	颜色	检查内容	工序	
1	7	5144852		1	白皱	①确认颜色正确 ②确认无毛刺	☒ ☒	LDA
2	7	5144853		1	白皱	①确认颜色正确 ②确认无毛刺	☒ ☒	LDA
3	7	5144854		1	白皱	①确认颜色正确 ②确认无毛刺	☒ ☒	LDA
4	7	5144855		1	白皱	①确认颜色正确 ②确认无毛刺	☒ ☒	LDA
5	7	5144856		1	黑皱	①确认颜色正确 ②确认无毛刺	☒ ☒	LDA
6	7	5144857		1	黑皱	①确认颜色正确 ②确认无毛刺	☒ ☒	LDA
7	7	5144858		1	白皱	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	LDA
8	7	5144860		1	白皱	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	LDA
9	7	5144861		1	黑皱	①确认颜色正确 ②确认无毛刺	☒ ☒	LDA
10	7	5144862		1	黑皱	①确认颜色正确 ②确认无毛刺	☒ ☒	LDA
11	7	5199295		1	白皱	①确认颜色正确 ②确认无毛刺	☒ ☒	LDA

12	7	5199296	 图 1 零件图	1	白皱	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	LDA
----	---	---------	--	---	----	----------------------------------	--	-----