










LPP63260801 (第7批)

A2A	台车	型式	简图	数量	颜色		备注	备注
1	6	5144811		1	白平	①确认颜色正确 ②确认无毛刺	☒ ☒	ALW 装配
2	6	5144675		1	白平	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☐ ☒	ALW 装配
3	6	5144696		1	白平	①确认颜色正确 ②确认无毛刺	☒ ☒	ALW 装配
4	6	5144754		1	白皱	①确认颜色正确 ②确认无毛刺	☒ ☒	ALW 装配
5	6	5144755		1	白皱	①确认颜色正确 ②确认无毛刺	☐ ☒	ALW 装配
6	6	5144756		1	白皱	①确认颜色正确 ②确认无毛刺	☐ ☒	ALW 装配
7	6	5144757		1	白皱	①确认颜色正确 ②确认无毛刺	☒ ☒	ALW 装配
8	6	5144817		1	白平	①确认颜色正确 ②确认无毛刺	☐ ☒	ALW 装配
9	6	5144832		1	白平	①确认颜色正确 ②确认无毛刺	☒ ☒	ALW 装配
10	6	5144833		2	白平	①确认颜色正确 ②确认无毛刺	☒ ☒	ALW 装配

11	6	5217736		1	白平	①确认颜色正确 ②确认无毛刺	☒ ☒	ALW	装配
12	6	5144820		2	白平	①确认颜色正确 ②确认无毛刺	☒ ☒	ALW	装配
13	6	5144750		1	白平	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	ALW	装配
14	6	5755827		1	#N/A	①确认颜色正确 ②确认无毛刺	☒ ☒	ALW	
15	6	5144742		1	白平	确认颜色正确 确认无毛刺 确认无变形 过丝确认	☒ ☒ ☒ ☒	ALW	装配
16	6	5144749		1	白平	①确认颜色正确 ②确认无毛刺	☒ ☒	ALW	装配
17	6	5144752		1	白平	①确认颜色正确 ②确认无毛刺	☒ ☒	ALW	装配
18	6	5238059		1	白平	①确认颜色正确 ②确认无毛刺	☒ ☒	ALW	装配
19	6	5607692		1	白皱	①确认颜色正确 ②确认无毛刺	☒ ☒	ALW	装配
20	6	5608808	 请检查零件上是否有油污，如有油污请用酒精清洗，并晾干后再进行装配。	1	白平	①确认颜色正确 ②确认无毛刺	☒ ☒	ALW	测漏 打胶遮 蔽装 配
21	6	5673062		1	白皱	①确认颜色正确 ②确认无毛刺	☒ ☒	ALW	打胶 装配